
UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



| | | Sundry Not | ices and Repo | orts on We | lls PH | 1: 50 | |
|----------------------|------------------------------------|--|--|---|---|---|---|
| | e of Well | | | 070 | Farmington, | 5. NM 6. | Lease Number SF-078510 If Indian, All. Tribe Name |
| | | | · · · · · · · · · · · · · · · · · · · | | <u>. </u> | 7. | Unit Agreement Na |
| | e of Opera | | | | | | |
| 爱 | URLI) ESOUI | | & GAS COMPAN | . | TET TO | | |
| | | OIL | & GAS COMPAN | • | 547463 | ે>ે8∙ | Well Name & Numb |
| | | ne No. of Opera | | AS | - Ann | | Oxnard 332 |
| PO | Box 4289, | Farmington, NM | 87499 (505) | 326 /97 00 | , May 5004 | (9'.) | API Well No. 30-045-27656 |
| 4. Loc | ation of W | ell, Footage, S | ec. T. R. M | - R | | 10. | Field and Pool |
| | | FEL, Sec.7, T- | | NMPM 😂 | | 53 | Basin FC |
| | | | | (E. 2) | ************************************** | 11. | County and State |
| | | | | |) (20 m in 67 %) | S. B. | San Juan Co, NM |
| 12. CH | ECK APPROP | RIATE BOX TO IN | DICATE NATURI | OF NOTIC | E, REPORT, | OTHER | DATA |
| Typ | e of Submi | | | Type of A | | | |
| | Notice | of Intent | Abandon Recomp | _ | Change of New Cor | | |
| | _X_ Subseq | uent Report | Plugging | | | | cacturing |
| · | | ~1 | | Repair | Water : | | |
| | Final . | Abandonment | Altering | | Conttore | on to | Injection |
| | | | | | Convers: | .011 00 | 111,0001011 |
| 13. | Describe P | roposed or Comp | X_Other | Install F | | | |
| | Describe P 10/08/03 10/09/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | w/tbg. 5, J-55 | SDFN. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | w/tbg. 5, J-55 | SDFN. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | w/tbg. 5, J-55 | SDFN. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | w/tbg. 5, J-55 | SDFN. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | w/tbg. 5, J-55 ND BOP, 5 1500, | SDFN. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | W/tbg. | SDFN. 5, 4.7#, OK. |
| | 10/08/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and ro | Install F ions ND WH, NU TIH w/10 , SN @ 327 | Dump D BOP. TOOH 14 jts 2.37! 11'. TOOH. 1 | W/tbg. 5, J-55 ND BOP, 5 1500 | SDFN. 5, 4.7#, OK. |
| | 10/08/03 10/09/03 | MIRU. TOOH W/ TIH. Clean ou EUE tbg. La NU WH. TIH | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and re eased. | Install Fions ND WH, NU TIH w/10 , SN @ 327 ods. PT th | Pump J BOP. TOOH 14 jts 2.37! 21'. TOOH. 1 | W/tbg. 5, J-55 ND BOP, 5 1500 | SDFN. 5, 4.7#, OK. PTED FOR RECORD EC 3 1 2003 |
| | 10/08/03 10/09/03 | MIRU. TOOH W/TIH. Clean ou EUE tbg. La NU WH. TIH RD, Rig Rel | X_Other leted Operation rods & Pump. t fill. TOOH nded @ 3299' W/pump and re eased. | Install Financions ND WH, NU TIH w/10 , SN @ 327 ods. PT the | Pump J BOP. TOOH 14 jts 2.37! 21'. TOOH. 1 | W/tbg. 5, J-55 ND BOP, 5 1500, FARMIBY | SDFN. 5, 4.7#, OK. PTED FOR RECORD EC 3 1 2003 INGTON FIELD OFFICE 12/10/03 |
| 14. Signed | I hereby conspace for | MIRU. TOOH W/TIH. Clean ou EUE tbg. La NU WH. TIH RD, Rig Rel | X_Other leted Operations rods & Pump. t fill. TOOH nded @ 3299' W/pump and re eased. foregoing is | Install Financial ions ND WH, NU. TIH w/10, SN @ 327 ods. PT the | BOP. TOOH 1 jts 2.37! 1'. TOOH. I og & pump to | W/tbg. 5, J-55 ND BOP, 5 1500, FARMIBY | SDFN. 5, 4.7#, OK. PTED FOR RECORD EC 3 1 2003 INGTON FIELD OFFICE |