

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	Huerfano Unit #52	Facility Type	Gas Well
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM SF-078518

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	4	T25N	R9W	1550'	North	1480'	West	San Juan

Latitude **36.43325° N** Longitude **107.79808° W**

NATURE OF RELEASE

Type of Release - Condensate and produced water	Volume of Release - 3 BBL condensate & 3 BBL produced water	Volume Recovered - none
Source of Release: Hole in separator	Date and Hour of Occurrence 11/14/07	Date and Hour of Discovery 11/14/07 - 12:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell - via email Mark Kelly - BLM - via email	RCVD NOV 20 '07 OIL CONS. DIV.
By Whom? Monica D. Johnson	Date and Hour - 11/16/07 - 11:30 a.m.	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company MSO (lease operator) discovered a spill of approximately 3 BBL condensate and 3 BBL produced water at the Huerfano Unit #52 on the afternoon of 11/14/07, due to a hole in the separator. The firetube cracked inside of the separator and caused the fluids to leak out of the firebox. All fluids remained on location, but none was recoverable, with all fluids soaking into the ground directly around the separator. Upon discovery, the well was shut in and the separator was blown down. A One-Call was made for excavation of the impacted soils for remediation.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained on location and affected an area 20' x 20' x 2' deep, with none recoverable. On November 16, 2007, 40 cubic yards of impacted soils were excavated and hauled offsite to a commercial landfarm for remediation, and the separator was repaired.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Monica D. Johnson</i>	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: <i>Brandon Kelly</i>	For: <i>Charlie Perrin</i>
Title: Sr. Environmental Scientist	Approval Date: 11/20/07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/16/07	Phone: 505-326-9829	

* Attach Additional Sheets If Necessary

nBP0734042749