

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DIST 3 Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company	Contact Monica D. Johnson
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-326-9829
Facility Name Quinn #4B	Facility Type Gas Well API # 30-045-30124
Surface Owner Federal	Mineral Owner Federal Lease No. NMSF-078511

LOCATION OF RELEASE

Unit Letter B	Section 19	Township T31N	Range R8W	Feet from the 735'	North/South Line North	Feet from the 2330'	East/West Line East	County San Juan
----------------------	-------------------	----------------------	------------------	---------------------------	-------------------------------	----------------------------	----------------------------	------------------------

Latitude 36.88871° Longitude 107.71587°

NATURE OF RELEASE



Type of Release - Condensate	Volume of Release - 20 BBL	Volume Recovered - 18 BBL
Source of Release: Condensate tank overflowed	Date and Hour of Occurrence 3/30/07	Date and Hour of Discovery 3/30/07 - 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - OCD - via email Mark Kelly - BLM - via email	
By Whom? Monica D. Johnson	Date and Hour - 3/30/07 - 3:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* **Our MSO discovered a condensate spill of an estimated 20 BBL at the Quinn #4B on 3/30/07, due to the condensate tank overflowing. This occurred because the well was shut-in around 3-20-07 for an engine swap on the pumping unit and when the well was brought back on, there was a surge of production. The tank had been gauged on 3-20-07 at 3'5" and was found full at 8'2" and overflowing. All fluids remained within the bermed area. The contents of the tank will be sold tomorrow. A vacuum truck recovered 18 BBL from the bermed area and has stored it in the pit until the tank is sold on Saturday. A roustabout crew will clean up the stained soils.**

Describe Area Affected and Cleanup Action Taken.* **All spilled fluids remained within the bermed area and 18 BBL were recovered. The area will be raked to naturally remediate any stained soils that remain inside the berm.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Monica D. Johnson	Approved by District Supervisor: 	
Title: Environmental Specialist	Approval Date: 4-3-07	Expiration Date:
E-mail Address: monica.johnson@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/30/07 Phone: 505-326-9829		

* Attach Additional Sheets If Necessary

nBP0711053786