Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

FEB 10 2 Hillease Serial No. BUREAU OF LAND MANAGEMENT NMSF 078925 SUNDRY NOTICES AND REPORTS ON WELLS Man of Land Man Conferment Allottee or Tribe Name Do not use this form for proposals to drill or to re-enfemantion Field Office abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Canyon Largo Unit 1. Type of Well 8. Well Name and No. Canyon Largo Unit # 437 Oil Well Gas Well Other 2. Name of Operator Huntington Energy, L.L.C. 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area Basin Dakota 405-840-9876 908 N.W. 71st St., Oklahoma Clly, OK 73116 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)
Nwsw, Lott, 1450' FSL & 800' FWL
Sac 25-T24N-R6W NMPM 11. Country or Parish, State Rlo Arriba Co., NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Water Shut-Off ✓ Notice of Intent Fracture Treat Reclamation Well Integrity Alter Casing New Construction Casing Repair Recomplete Other Subsequent Report Change Plans Plug and Abandon ✓ Temporarily Abandon Water Disposal V8 Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Huntington Energy, L.L.C. respectfully requests to TA the above referenced well due to uneconomic production and offset results of the CLU 477 Mancos recompletion, which was uneconomic. The TA will give necessary time to evaluate potential uphole zones. Cancel The following is the TA procedure: 1. MICU. ND Wellhead, NU BOP 2. POOH with 2 3/8" tubing. RIH with 4 1/2" CIBP, 2 3/8" tubing and set at 6,250'. (2/7/10: Unable to set plug. Inadvertently set plug at 5505', rel Plug. Would not test. Will drill out plug. Reset plug at 6200'. Load hole with 2% KCL water. Test plug to 500 psi. Monitor for 30 minutes. 3. COOH with tubing and lay down. 4. ND BOP, NU wellhead, Retest to 500 psi. Monitor results. Release rig. 5. Call BLM & NMOCD & set up Mechanical Integrity Test. Pressure test casing to 500 psi and monitor for 30 minutes. Record on a chart. RCVD MAR 3'10 Notify NMOCD 24 hrs OIL CONS. DIV. prior to beginning THE APPROVED PROPERTY operations Must comply with NMOCD Rules 19.15.25.12, 19.15.25.13 and 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Catherine Smith 19.15.25.14 Title Date 02/08/2010 Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Original Signed: Stephen Mason FEB 1 0 2010 Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false.

fictitious or fraudulent statements or representations as to any matter within its jurisdict

(Instructions.on.page.2)