


30-045-08970

Inspected 10-26-59  
AR - [Signature]Budget Bureau 42-R358.3.  
Approval expires 12-31-55.Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

Land Office Santa FeLease No. 078619Unit SE 1/4 Sec. 31UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

RECEIVED

DEC 31 1954

U.S. GEOLOGICAL SURVEY

FARMINGTON, NEW MEXICO

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 13, 1954

Well No. Pipkin 1 is located 790 ft. from [N] line and 990 ft. from [E] line of sec. 31SE 1/4 (1/4 Sec. and Sec. No.) 30 N. (Twp.) 11 W. (Range) N.M.P.M. (Meridian)

Wildcat (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran Homco Free Point survey on 7" casing. Cut and recovered 916' of casing. Plugged well with heavy rotary mud and cement. Cement plugs installed by Halliburton at the following depths: 3295 to 2930, 950 to 700, 480 to 420, plugs in 10-3/4" surface casing @ 152 to 102 and 10 to 0. Installed 4" marker extending 4 feet above ground.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Claude M. CarrollAddress Box 337, Farmington, New MexicoBy R. Owen  
Roy Owen,Title Business Manager