

RECEIVED

Form 3160-5  
(February 2005)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCT 05 2010

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

Farmington Field Office

5. Lease Serial No.  
NM36096

6. If Indian, Allottee or Tribe Name

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**

SUBMIT IN TRIPLICATE - Other instructions on page 2.

## 1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

## 2. Name of Operator

Pride Energy Company

## 3a. Address

P.O. Box 701950, Tulsa, OK 74170-1950

## 3b. Phone No. (include area code)

918-524-9200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Unit Letter B: 1.980' FEL and 660' FNL of Section 12-20N-3W

## 7. If Unit of CA/Agreement, Name and/or No.

## 8. Well Name and No.

San Isidro 12-2

## 9. API Well No.

30-043-20721

## 10. Field and Pool or Exploratory Area

Rio Puerco

## 11. Country or Parish, State

Sandoval County, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

## TYPE OF SUBMISSION

## TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☒ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Final Abandonment Notice☐ Casing Repair☐ New Construction☐ Recomplete☐ Other☐ Change Plans☐ Plug and Abandon☒ Temporarily Abandon☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

This well was Temporarily Abandoned on September 24, 2010. Bridge plug was set within 50' of the top perf (top perf is at 3,910') and then a Mechanical Integrity Test was successfully performed by Wilson Service Co., Inc, P.O. Box 1619, Farmington, NM. 87499. The chart is attached to this Form 3160-5. 24-hour notice was provided to the BLM's Farmington, NM office and also to the NMOCD's office in Aztec, NM, however no representative from either office was able to witness the Temporarily Abandonment of this well.

NMOCD T/A EXPIRES 9-24-2015 - FEDERAL EXPIRATION MAY VARY  
CONTACT NM BLM FOR FEDERAL EXPIRATION INFORMATION.

RCVD OCT 8 '10

OIL CONS. DIV.

DIST. 3

## 14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)

Matthew L. Pride

Title President of Pride Production Co., Inc. General Partner of Pride Energy Co

Signature

Matthew L. Pride

Date

9/30/10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

## Approved by

Title

Date

OCT 05 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD

