Form 3160 DEPARTMI		TED STATES ENT OF INTERIOR AND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
SUNDRY NOTICE AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals ADV 09 2010			5.	Lease Designation and Serial No. NMSF-078890	
			6.	If Indian, Allottee or Tribe Name N/A	
	SUBMIT IN 1	Farmington Field Off Bureau of Land Manage	od. men	If Unit or CA, Agreement Designation Rosa	
1.	Type of Well Oil Well X Gas Well Other	Bureau of Land Manager	8.	Well Name and No. Rosa Unit #630	
2.	Name of Operator WILLIAMS PRODUCTION COMPANY		9.	API Well No. 30-039-29508	
3.	3. Address and Telephone No. PO BOX 640 Aztec, NM 87410-0640 634-4208			Field and Pool, or Exploratory Area Blanco MV/Basin MC/ Basin DK	
4.	Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface: 2480' FNL & 2230' FEL Sec. 7, T31N, R4W			County or Parish, State Rio Arriba, NM	
	CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OF	R OTHER DATA	
	TYPE OF SUBMISSION TYPE			OF ACTION	
X Subsequent Report Plugg Casin Final Abandonment Alteri		Abandonment Recompletion Plugging Back Casing Repair Altering Casing X Other FIRST DELIVERY- PERMANENT		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose	
				Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13.	13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*				
This N	/IC well was 1 st delivered on 11/8/10	@ 1135 hrs. The initial rate was 519 mcf	fd.		
Meter	Code #: 82120017				
Project Type: FIRST DELIVERY PERMANENT					
Tubing Pressure: 3000+					

Line Pressure: 150

14.

Casing Pressure: 3000+

Permanent line to WFS