

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires July 31, 2010

JAN 13 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
Contract 111

6. If Indian, Allottee or Tribe Name
Jicarilla
Bureau of Land Management
Farmington Field Office

SUBMIT IN TRIPLICATE -- Other instructions on page 2.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
D.J. Simmons, Inc.

3a. Address
1009 Ridgeway Place, Ste 200, Farmington, NM 87401

3b. Phone No. (include area code)
505-326-3753

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No
Jicarilla H 111

9. API Well No.
30-039-22256

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2150' FSL, 1850' FEL
Sec 5, T24N, R4W

10. Field and Pool or Exploratory Area
Otero Chacra

11. Country or Parish, State
Rio Arriba, NM

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☒ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13 Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

- 1 - Set CIBP w/2sx cement @ 6000' +/-
- 2 - Run CBL from stage tool @ 3894' to TOC
- 3 - Perf Chacra from 3662' to 3777' in select intervals
- 4 - Break down perfs and frac w/fluid & sand
- 5 - Clean up
- 6 - Return to production

RCVD JAN 14 '10

OIL CONS. DIV.

DIST. 3

RECEIVED

JAN 8 2010

HOLD C104 FOR C-102 and NSL order for Otero Chacra

Bureau of Land Management
Durango, Colorado

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Laura Tucker

Title Agent

Signature

Date

1-5-10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

JAN 11 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOC