

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. SF-078106	
2. Name of Operator BP AMERICA PRODUCTION COMPANY		6. If Indian, Allottee or Tribe Name	
3a. Address P.O. BOX 3092 ROOM 19.178 HOUSTON, TX 77253		7. If Unit or CA/Agreement, Name and/or No.	
3b. Phone No. (include area code) Ph: 281.366.4081 Fx: 281.366.0700		8. Well Name and No. GALLEGOS CANYON UNIT 229E	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 21 T28N R12W NESE 1820FSL 1080FEL		9. API Well No. 30-045-23900	
		10. Field and Pool, or Exploratory WILDCAT FARMINGTON SAND	
		11. County or Parish, and State SAN JUAN COUNTY, NM	

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

On 4/17/02 BP America ran a Mechanical Integrity Test on the above mentioned well. The MIT was approved 5/30/02. This approval was given with a stipulation saying: "Hold for Fruitland Coal infill approved to 12/31/02". After much deliberation it is determined there is no future production for this well.

Please grant permission to P&A this wellbore per the attached procedure.

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #16786 verified by the BLM Well Information System For BP AMERICA PRODUCTION COMPANY, sent to the Farmington Committed to AFMSS for processing by Steve Mason on 12/10/2002 ()	
Name (Printed/Typed) CHERRY HLAVA	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 12/10/2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By Original Signed: Stephen Mason	Title	Date 12/12/02
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

NMOCD

GCU 229E
Unit I Section 21 R28N - T12W
API # 30-045-23900
San Juan County, NM

Reason for work:

This well is subject to BLM demand letter and will be plugged and abandoned.

Procedure:

NOTE: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.34 ppg, sufficient to balance all exposed formation pressures.

1. Install and test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Marathon regulations. Notify agencies 24 hours prior to commencing plugging activities.
2. MIRUSU. Conduct safety meeting with all personnel on location. NU relief line. Blow down well, and kill with fresh water if necessary. ND WH and NU BOP and test.
3. TIH & tag cement plug @ 2800'. Load hole & pressure test to 500 psi. PU to 1430'.
4. Plug #1 (Fruitland & Pictured Cliffs: 1430' - ^{1028'}~~1310'~~). Spot ~~10~~ sack balanced cement plug. PU to 347'.
5. Plug #2 (surface casing shoe to surface: 347' - surface). Mix & pump cement. Circulate to surface (approximately 28 sacks).
6. ND BOP & RD floor. Dig cellar and cut off wellhead. Top off casing strings as needed. RD. Cut off anchors and install dry hole marker.
7. Contact FMC and ship surface equipment to yard or other location per instructions.
8. Provide workorder to Vance Norton for reclamation.
9. Rehabilitate location according to BLM or State requirements.

Josue Villesca
281-366-2950 office
281-366-7099 fax
713-416-8081 mobile

Formation Tops

Pictured Cliffs	1360
Lewis	1379
Mesaverde	2958
Mancos	4128
Gallup	5016
Greenhorn	5810
Graneros	5910
Dakota	5982

GCU 229E
 Unit I Section 21 T28N - R12W
 API # 30-045-23900
 San Juan County, NM

09 Dec 2002
 JV

