## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



APR 08 2011

with the same of t	Sundry Notices and Rep	orts on Wells			. Field Office
				Farming Townson Of	ton Field Office Land Managamen Lease Number
				Buleagion	
	TO CANAL IN				SF-079383
•	Type of Well			6.	If Indian, All. or
	GAS				Tribe Name
			% RECEIVED		w
	N 60 /		A89 A A	3. 7.	Unit Agreement Nam
	Name of Operator		(6) Z	E.	San Juan 30-6 Unit
	BURLINGTON		& BECEIVEL	) 📆	
	RESOURCES OIL	& GAS COMPANY LP	1 . 0	8 19 8	
			2 APR 2011	8.	Well Name & Numbe
	Address & Phone No. of Open	rator	OIL CONS. DIV. DIST.	, N/	San Juan 30-6 Unit 90
	•		OIL CONS. DIV. DISI.	3 N/	
	PO Box 4289, Farmington, NN	4 87499 (505) 326-9700	\@.	9. الأباع.	API Well No.
	, , , , , , , , , , , , , , , , , , , ,		620- 78	<u> </u>	
			OIL CONS. DIV. DISI.		30-039-27011
	Location of Well, Footage, Se	c., T, R, M	•		20 322 <b>210 1</b> 1
	, 3,			10.	Field and Pool
	Unit H (SENE), 2515' FNL &	180' FEL, Section 26, T3	30N, R7W, NMPM		Basin Dakota
		,	, ,	,	
		•	•	11.	County and State
					Rio Arriba, NM
• '	CHECK APPROPRIATE BO Type of Submission Typ Notice of Intent	oe of Action Abandonment	Change of Plans	<u>x</u>	Other – Tubing Repair
	X Subsequent Report	Recompletion	New Construction		
	X Subsequent Report	Plugging Casing Repair	Non-Routine Frac	turing	
	Final Abandonment	Altering Casing	Conversion to Inje	ection	
	Describe Proposed or Comple	-			
19 rc	Describe Proposed or Comple /2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ O'. ND BOPE. NU WH. RD RR	H. NU BOPE. PT BOPE.  Perform MIT & Chart c. clean. 3/7/11 RIH w/ 243	to 560#/30min. Test - Ok	K. John Durha	m w/ OCD witnessed te
19 irc <b>1d</b> 559	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.	to 560#/30min. Test - Ok	K. John Durha	m w/ OCD witnessed tes
19 rc id 559	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ P'. ND BOPE. NU WH. RD RR	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.	to 560#/30min. Test - Ok Bjts, 2 3/8", 4.7#, J-55 tbg s	K. John Durha	m w/ OCD witnessed terew set depth) w/ F-Nipple
19 rc d 559 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ P'. ND BOPE. NU WH. RD RR  I hereby certify that the foreget for Federal or State Office Space for Federal or State Office.	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal	to 560#/30min. Test - Ok Bjts, 2 3/8", 4.7#, J-55 tbg s	K. John Durha set @ 7561' (N	m w/ OCD witnessed terew set depth) w/ F-Nipple
19 rc d 59 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ P'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg  ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal	to 560#/30min. Test - Ok Bjts, 2 3/8", 4.7#, J-55 tbg s Tafoya Title: Staff	K. John Durha set @ 7561' (N	m w/ OCD witnessed tes ew set depth) w/ F-Nipple
19 rc d 59 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ P'. ND BOPE. NU WH. RD RR  I hereby certify that the foreget for Federal or State Office Space for Federal or State Office.	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:	to 560#/30min. Test - Ok Bjts, 2 3/8", 4.7#, J-55 tbg s Γafoya Title: Staff	K. John Durha set @ 7561' (N	m w/ OCD witnessed terew set depth) w/ F-Nipple
19 re d 59 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ P'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:  n knowingly and willfully to make any depa	to 560#/30min. Test - Ok  Bjts, 2 3/8", 4.7#, J-55 tbg s  Tafoya Title: Staff	K. John Durha set @ 7561' (N	m w/ OCD witnessed te ew set depth) w/ F-Nipple chnician Date 4/8/
19 re d 59 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ D'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:  n knowingly and willfully to make any depa	to 560#/30min. Test - Ok  Bjts, 2 3/8", 4.7#, J-55 tbg s  Tafoya Title: Staff	K. John Durha set @ 7561' (N Regulatory Te	m w/ OCD witnessed te ew set depth) w/ F-Nipple chnician Date 4/8/
19 rc d is 59 hi	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ D'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:  n knowingly and willfully to make any depa	to 560#/30min. Test - Ok  Bjts, 2 3/8", 4.7#, J-55 tbg s  Tafoya Title: Staff	K. John Durha set @ 7561' (N Regulatory Te	m w/ OCD witnessed te ew set depth) w/ F-Nipple chnician Date 4/8/c
19 re d (55)	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ D'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:  n knowingly and willfully to make any depa	to 560#/30min. Test - Ok  Bjts, 2 3/8", 4.7#, J-55 tbg s  Tafoya Title: Staff	K. John Durha set @ 7561' (N Regulatory Te	m w/ OCD witnessed terew set depth) w/ F-Nipple chnician Date 4/8/6
irc nd 559 1.	/2011 MIRU AWS 748. ND W clean. 3/1/11 Set RBP @ 3086' has chart. POOH w/ RBP. Circ D'. ND BOPE. NU WH. RD RR  I hereby certify that the foreg ed	H. NU BOPE. PT BOPE.  Perform MIT & Chart  c. clean. 3/7/11 RIH w/ 243  @ 17:00hrs on 3/7/11.  oing is true and correct.  Crystal  ce use)  Title  ny:  n knowingly and willfully to make any depa	to 560#/30min. Test - Ok  Bjts, 2 3/8", 4.7#, J-55 tbg s  Tafoya Title: Staff	K. John Durha set @ 7561' (N Regulatory Te	m w/ OCD witnessed terew set depth) w/ F-Nipple chnician Date 4/8/6

NMOCD

PC

SM