

District SOUTH	Field Name FC/PC COM	API / UWI 3003930881	County RIO ARRIBA	State/Province NEW MEXICO	
Original Spud Date 1/26/2011	Surface Legal Location 034-028N-006W-J	East/West Distance (ft) 2,075.00	East/West Reference FEL	North/South Distance (ft) 2,102.00	North/South Reference FSL

Well Config: VERTICAL - Original Hole: 5/27/2011 7:32:58 AM

Schematic - Actual

ftKB (MD)

15				2-1, Casing Hanger, 5 1/2, 4.892, 15, 1.1
16				
17				2-2, Pup Joint, 5 1/2, 4.892, 16, 1.4
18				1-1, CASING HANGER, 9 5/8, 9.001, 15, 3.1
200				1-2, CASING JOINTS, 9 5/8, 9.001, 18, 181.6
201				1-3, FLOAT COLLAR, 9 5/8, 9.001, 200, 1.4
232				1-4, CASING JOINTS, 9 5/8, 9.001, 201, 30.5
233				1-5, SAW TOOTH COLLAR, 9 5/8, 9.001, 232, 0.9
238				
2,760				1-1, Tubing, 2 3/8, 1.995, 15, 3,436.4
2,841				
2,985				2-3, Casing Joints, 5 1/2, 4.892, 18, 2,967.3
2,995				2-4, Marker Joint, 5 1/2, 4.892, 2,985, 10.1
3,179				
3,208				2-5, Casing Joints, 5 1/2, 4.892, 2,995, 213.6
3,214				2-6, Pup Joint, 5 1/2, 4.892, 3,208, 5.3
3,242				
3,244				Perforated, 3,242-3,343, 4/5/2011
3,343				
3,386				Perforated, 3,386-3,454, 4/5/2011
3,427				2-7, Casing Joints, 5 1/2, 4.892, 3,214, 213.6
3,451				1-2, Tubing Pup Joint, 2 3/8, 1.995, 3,451, 2.0
3,453				
3,454				
3,457				
3,466				1-3, Tubing, 2 3/8, 1.995, 3,453, 31.2
3,478				Perforated, 3,466-3,478, 4/5/2011
3,485				
3,486				1-4, Profile Nipple, 2 3/8, 1.785, 3,485, 1.1
3,487				1-5, Mule Shoe W/ EXP-CHK, 2 3/8, 1.785, 3,486, 1.0
3,617				
3,626				2-8, Casing Joints, 5 1/2, 4.892, 3,427, 198.8
3,627				2-9, Float Collar, 5 1/2, 4.892, 3,626, 0.9
3,669				2-10, Casing Joints, 5 1/2, 4.892, 3,627, 42.3
3,670				2-11, Float Shoe, 5 1/2, 4.892, 3,669, 0.9
3,695				

