

GOVERNOR

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

February 12, 1986

Mr. Gavino Perez Tesoro Petroleum Corp. 8700 Tesoro Dr. San Antonio, TX 78286

Re: Santa Fe Railroad B #38		M-05-17N-08W
Hanson #19		K - 06 - 17N - 08W
Hanson #21		K-06-17N-08W
Hanson #18		M-06-17N-08W
Hanson #43		M - 06 - 17N - 08W
Hanson Federal #34		O-06-17N-08W
Santa Fe Railroad #10		B-07-17N-08W
Santa Fe Railroad #22		D-07-17N-08W
Santa Fe Railroad #24		F-07-17N-08W
Hospah Sand Unit #49		A-01-17N-09W
Santa Fe Pacific Railroad	#A-87	P-01-17N-09W
Santa Fe Railroad #54-L		A-12-17N-09W
Hospah Sand Unit #68		B-36-18N-09W
Hospah Sand Unit #69		E-36-18N-09W
Hospah Sand Unit #64		H-36-18N-09W
Hospah Sand Unit #70		L-36-18N-09W
Hospah Sand Unit #65		P-36-18N-09W

Dear Mr. Perez:

A letter, dated November 21, 1985, directed you to repair the referenced wells within 60 days. To date we have not received any Division C-103 forms showing intent to repair casing, nor has any remedial action commenced. You are hereby directed to submit forms C-103, and begin repairs on the referenced wells within 30 days. A form C-103 is enclosed for your reference.

Yours truly,

Carolyn J. Taplin Field Representative

CJT/dj

xc: Prentiss Childs UIC File Operator File √Well File