

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Hospah Sand Unit
2. Name of Operator Tesoro Petroleum Corporation	8. Farm or Lease Name
3. Address of Operator 8520 Crownhill, San Antonio, Texas 78209	9. Well No. 1
4. Location of Well ** UNIT LETTER <u>A</u> <u>1050</u> FEET FROM THE <u>East</u> LINE AND <u>1020</u> FEET FROM THE <u>North</u> LINE, SECTION <u>1</u> TOWNSHIP <u>17N</u> RANGE <u>9W</u> NMPM.	10. Field and Pool, or Wildcat Upper Hospah Sand
15. Elevation (Show whether DF, RT, GR, etc.) 6935' GL	12. County McKinley


16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon well as follows:

Set 222' cement plug across Hospah Sand and perforate below Seven Lakes at approximately 560' GL. To run cast iron retainer on wire line and set at approximately 240'. Will pump cement through retainer in sufficient volume to cover Seven Lakes inside and outside casing. Will set 10' plug in top and install dry hole marker.

\*\*This was originally filed as Santa Fe-Hurst #1 at a location 829' East of the Center Line and 495' South of the North Line of Section 1, T-17-N, R-9-W.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. H. Lerman TITLE Mgr. of Production Engineering DATE Sept. 21, 1971

Original Signed by Emery C. Arnold TITLE SUPERVISOR DIST. #3 DATE SEP 21 1971

APPROVED BY \_\_\_\_\_ CONDITIONS OF APPROVAL, IF ANY: