

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry</b>	7. Unit Agreement Name
2. Name of Operator <b>Morris R. Antweil</b>	8. Farm or Lease Name <b>Leah</b>
3. Address of Operator <b>P. O. Box 2010 Hobbs, New Mexico 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>A</b> , <b>660</b> FEET FROM THE <b>N</b> LINE AND <b>660</b> FEET FROM THE <b>E</b> LINE, SECTION <b>34</b> TOWNSHIP <b>17N</b> RANGE <b>8W</b> NMPM.	10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>6900 KB</b>	12. County <b>McKinley</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Received oral permission to P & A from O.C.C.**

**T.D. 2860**

**Set 100' plug from 2600' to 2700'**  
**Set 150' plug from 1700' to 1850'**  
**Set 100' plug from 470' to 570'**  
**Set 50' plug from 350' to 400'**  
**Set Surface plug and set dry hole marker**  
**W/Operator, Lease name & Location on the marker.**  
**Clean up location, level same.**  
**Location ready for inspection.**




18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jan L. Hays</u>	TITLE <u>Agent</u>	DATE <u>7/19/71</u>
APPROVED BY <u>Elmer C. Underhill</u>	TITLE <u>Sup. Dist. III</u>	DATE <u>10-21-71</u>
CONDITIONS OF APPROVAL, IF ANY:		

NEW MEXICO OIL CONSERVATION COMMISSION  
1000 RIO BRAZOS ROAD  
Aztec, New Mexico

Morris R Antweil  
PO Box 2010  
Hobbs, New Mex.



RE: Plugging Reports

Gentlemen:

Form C-103, Notice of Intention to Plug, your Lease 1 A-34-17N-8W  
was approved on 7-15-71. Your subsequent notice of plugging cannot be  
approved until a commission representative has made an inspection of the location  
to see:

- (1) all pits have been filled and leveled;
- (2) a steel marker, 4" in diameter and approximately 4' above mean ground level, must be set in concrete, this marker must have the quarter-quarter section or unit designation, section, township and range numbers, which shall be permanently stenciled or welded on the marker;
- (3) the location shall be cleared and cleaned of all junk;
- (4) the dead man wires must be cut.

The above are the minimum requirements.

Please notify us by filling in the blank form below when this work has been done so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION COMMISSION

By Ernest C. Arnold

Fill in below and return:

Lease 1 A-34-17N-8W  
Lease Well No. Unit-S-T-R

is ready for your inspection and approval.

Morris R. Antweil  
Operator

Jim L. Ray - Seal  
Name and title

Location inspected 10-21-71  
OK. BA