

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 623	
2. NAME OF OPERATOR James P. Woosley		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 1227, Cortez, CO 81321		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 145' FNL & 642' FNL		8. FARM OR LEASE NAME Federal Milk Lake	
14. PERMIT NO. Oct. 17, 1978		9. WELL NO. 2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6258 GL		10. FIELD AND POOL, OR WILDCAT W C	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 18; T19N R13W NW 1/4 NW 1/4	
		12. COUNTY OR PARISH McKinley	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged & abandoned as follows:

1. set cement plug from 906' back to 585' with 44 sks.
2. staged mud from 585' back to 43'
3. set cement plug from 43' to surface with 8 sks.
4. cleaned and leveled location and pits
5. erected plugged and abandon marker with 1 sks.
6. will reseed location between July 1 & Sept. 15.

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED James P. Woosley TITLE operator

DATE 12/17/82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED

SEP 29 1983

M. Milenzach
AREA MANAGER

*See Instructions on Reverse Side

NM000