Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

	Expires:	March	31, 193	95
1	Decimat	ion and	Carial	No

,		3.00.000
Approved by	Title	ACCEPTED FOR RECORL
Signed Chis space for Federal or State office use)	Tide President	
Please see attachment for P	& A procedures. SEP RECE OLOG ON ON ON ON ON ON ON ON ON	•
Subsequent Report X Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state all give subsurface locations and measured and true vertical	Recompletion Plugging Back Casing Repair Altering Casing Other Depriment details, and give pertinent dates, including estimated date of starting depths for all markers and zones pertinent to this work.)*	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) g any proposed work. If well is directionally drilled,
TYPE OF SUBMISSION Notice of Intent	Abandonment TYPE OF ACTION	Change of Plans
0, 2310' FEL, 990' FSL, Sec. 6 CHECK APPROPRIATE BOX(s)	McKinley, NM RT, OR OTHER DATA	
3 Address and Telephone No. P.O. Box 1680 Hobbs, NM 88241 4. Location of Well (Footage, Sec., T., R., M., or Survey Desc.)	30-031-20597 10. Field and Pool, or Exploratory Area Hospah Lower Sand South 11. County or Parish, State	
2. Name of Operator BC & D OIL AND GAS CORP.	HANSON FED 34 9. API Well No.	
1. Type of Well Oil Well Gas Well Well Woller WIW	8. Well Name and No.	
SUBMIT I	7. If Unit or CA, Agreement Designation	
SUNDRY NOTICES A Do not use this form for proposals to drill Use "APPLICATION FOR	NM 052931 6. If Indian, Allottee or Tribe Name	
BUREAU OF LA	5. Lease Designation and Serial No.	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, ficutious of fraudulent statements or representations as to any matter within its jurisdiction.

HANSON WELL NO. 34 30-031-20597 SEC.6, T17N,R8W

8/01/01

MIRU PLUGGING EQUIPMENT

8/02/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, RLS. PKR, POOH AND LAY DOWN TBG AND PKR., PU AND TIH WITH 2 7/8" TBG. OPEN ENDED TO 1587' (PERFS @ 1566'- 1582') SECURE WELL, SHUT IN DUE TO RAIN.

8/06/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, COULD NOT MIX CEMENT PROPERLY DUE TO EQUIPMENT PROBLEMS, SECURE WELL, SHUT IN

8/08/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIX 105 SXS. CLASS "B" NEAT CMT., ESTABLISH CIRCULATION AND PUMP 105 SXS. CMT. (123.9 CUBIC FEET) FLUSH WITH WATER, POOH WITH TBG., SECURE WELL, SI, WOC.

8/09/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIRU WIRE LINE TRUCK, TIH WITH TOOLS AND TAG TOC @ 893', FREEPOINT AND CUT CSG. @ 621', COULD NOT PULL CSG., CIRCULATE DOWN 5 1/2" CSG AND OUT 8 5/8" SURFACE CSG., STILL COULD NOT PULL CSG., TIH WITH TBG., TAG TOC @ 893', MIX 30 SXS. CLASS "B" NEAT CMT. ESTABLISH CIRCULATION AND PUMP 30 SXS. CLASS "B" CMT (35 CUBIC FEET), FLUSH WITH 3.7 BBLS WATER, POOH WITH TBG. TO 630' AND CIRCULATE WELL, POOH WITH TBG, SECURE WELL, SI, WOC.

8/15/01

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH WITH TBG. TO TAG TOC @ 700', POOH WITH TBG., SECURE WELL WAIT ON CEMENT TO BE DELIVERED TO LOCATION.

8/ /01

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIX 200 SXS. CLASS "B" NEAT CMT. (236 CUBIC FEET), ESTABLISH CIRCULATION DOWN 5 1/2" CSG. FROM SURFACE TO 621' AND OUT 8 5/8" WITH GOOD RETURNS TO PIT, PUMP 187 SXS. CMT. WITH GOOD SLURRY TO PIT, RIG DOWN EQUIPMENT, TOP OFF CSG UNTIL TOP PLUG WAS STABLE, RIG DOWN AND MOVE ALL PLUGGING EQUIPMENT, INSTALL P&A MARKER, CLEAN LOCATION, WELL P&AD.