

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

API # (assigned by OCD)

1. **Type of Well**
OIL

5. **Lease Number**

2. **Name of Operator**
Geo Engineering

6. **State Oil & Gas Lease #**

3. **Address & Phone No. of Operator**
P.O.Box 2966
Santa Fe, NM 87505

7. **Lease Name/Unit Name**
State

8. **Well No.**
#25

4. **Location of Well, Footage, Sec., T, R, M**
Sec. 28 T-20-N, R-9-W, NMPM, McKinley County
Unit B

9. **Pool Name or Wildcat**

10. **Elevation:**

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, will plug and abandon said well according to the attached procedure prepared by NMOCD.

This work will be in accordance with State of New Mexico Contract No. 98-521.25-059.

RECEIVED
JAN 22 1998

OIL CON. DIV.
DIST. 3

SIGNATURE William F. Clark Contractor
William F. Clark

December 30, 1997

(This space for State Use)
Approved by Johnny Robinson Title DEPUTY OIL & GAS INSPECTOR, DIST. #3

Date JAN 22 1998

COMPANY Geo Engineering		PROPERTY NAME State		WELL NO. 25
DATE	LOCATION (ULSTR) B-28-20N-09W	FOOTAGE		
API NO.		POOL		
4 1/2" csg with wellhead 303' T.O.C. 520' 526' Perfs 40CF 4 1/2 535'				
CASING RECORD: 4 1/2 csg. @ 535' Calc. T.O.C. @ 303' n/o fbg				

COMPANY Gen Engineering		PROPERTY NAME State	WELL NO. 25
DATE	LOCATION (ULSTR) B-28-20N-09W	FOOTAGE	
API NO.		POOL	

4 1/2" csg with
wellhead

CASING RECORD:

4 1/2 csg. @ 535'
Calc. T.O.C. @ 303'

1. Determine depth of well
2. If depth is 300' or more continue with procedure. If not clean out csg to 300'
3. ~~4.~~ Put @ 300' & 30'
4. Git with slickline & load csg with cement
5. Put with slickline & pump cement down the csg & circ. cement to the surf.
6. Install dry hole marker

303'
T.O.C.

520'
526' Perfs

40CF

4 1/2

535'