Pot Mesa #8

H-10-20N-6W

MERRION OIL & GAS CORP.

F

30-031-20896

12-26-85

| F. Loc | 1780/N; 855 | 5/E | Elev | Elev. 6904 GL Spd. Cu. ft. | | | CompTD | | | P8 | | |
|-----------------------|---------------------|--------------------|----------|----------------------------|---------------------------|----------|---------------|----------|--|----------------|--|--|
| Cosing S Csg.Perf. | ew [·] | Cu. ft. Sx. Int | | w | Cu. ft. Sx. Pr Prod. Stim | | w. | w | Cu. ft. Sx, T. | | | 7 Gas |
| I.P | BO/D MCF/D After | Hrs. SICP. | P: | SI After | | | | | | | | A N S |
| | TOPS | NITD X | | Well Log | | TEST DAT | | | | | | |
| Ojo Alamo | | C-103 | · | Plat X | | Schd. | PC | Q | PW | PD | D | Ref.No. |
| Kirtland | | C-104 | | Electric Log | | | | <u> </u> | | 1 | | 1 |
| Fruitland | | | T | C-122 | | | | <u> </u> | | | | + |
| Pictured Cliffs | | Ditr | <u> </u> | Dfa | | | | | | - | 1 | |
| Chacra | | Datr | | Doc | | | | | ļ | | | |
| Cliff House | | <u> </u> | ···· | | | | | | | | | |
| Menefee | | 1 | | | | | | | | | - | |
| Point Lookout | | 1 | | | | | | | | | | <u> </u> |
| Mancos | | 1 | | | | | | | - | | | |
| Gallup | | 1 | | | | | | | | | | |
| Greenhorn | | 1 | | | | | | | | | | |
| Dakota | | 1 | | | | | | | | <u> </u> | | ļ <u> </u> |
| Entrada | | 1 | | | | | | | | _ | | <u> </u> |
| | | | | Acr | es 40 | | | | | | | |
| P • • WC MV | Co. MCKS | 10 i 20i | NR 6W U | | | Corp. | ا ــــــــــا | P | ot Mes | | No. | <u>1 </u> |

Caller Service 4104 Farmington, New Mexico 87499

JAN 22 1987

Nerrion Oil and Gas Corporation F.O. Box 840 Farmington, NH 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

The state of the s

- 1. No. 6 Pot Fesa, located SE/4NW/4 sec. 10, T. 20 N., R. 6 W., McKinley County, New Mexico, on lease NM-24964.
- 2. No. 7 Pot Fesa, located NW/4NW/4 sec. 10, T. 20 H., R. 6 W., McKinley County, New Mexico, on lease NM-24964.
- 3. No. 8 Pot Mesa, located SE/4NE/4 sec. 10, T. 20 N., R. 6 N., McKinley County, New Mexico, on lease NM-24964.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, we will presume that no construction occurred. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely,

isi John L. Keiler

FOR Area Manager

3 Enclosures

cc: NMOCD (2) OIL CON DIST. 3 DIV.

ACTIOONED LOCATION