

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well OIL	API # (assigned by OCD) 30-031-60028
2. Name of Operator Geo Engineering	5. Lease Number Fee
3. Address & Phone No. of Operator P.O.Box 2966 Santa Fe, NM 87505	6. State Oil & Gas Lease #
4. Location of Well, Footage, Sec., T, R, M Sec. 20 T-20-N, R-9-W, NMPM, McKinley County Unit P, 1058' FSL and 860' FEL 1045	7. Lease Name/Unit Name Santa Fe Pacific I
	8. Well No. #12
	9. Pool Name or Wildcat
	10. Elevation:

Type of Submission	Type of Action
☐ Notice of Intent	☒ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☐ Other -

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut off
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, plugged and abandoned said well according to the attached Daily Report.

This work was completed under State of New Mexico Contract No. 98-521.25-059.

RECEIVED
MAR 13 1998

SIGNATURE William F. Clark Contractor OIL CON. DIV. March 4, 1998
DIST. 3

(This space for State Use)
Approved by Johnny Robinson DEPUTY OIL & GAS INSPECTOR, DIST. #3 Title DATE MAR 13 1998

Daily Report

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No _____

Date 2-23-90Well No Santa Fe Pacific 1-42 Location P-20-20N-09W Company Geo Engineering

FROM	TO	DESCRIPTION OF OPERATION
2-11-98		
12:30	14:00	Run in hole w/wt & tag AT 335'
2-17-98		
5:15	5:30	move to well set-up PT105 & pump down 2" csg w/10 BBL AT 1 1/2 BPM AT 300 PSI DRAIN-up PT105 SDFD
2-18-98		
8:00	8:30	START equipment
8:30	8:45	Plug #1 mix 14SKS disp to 300' WOC shut in well w/250 PSI
8:45	9:45	WOC Run wt + Tag Plug #1 AT 314' Perf 1 hole AT 305 w/1 1/16 hiwire shut
9:45	10:00	Pump into Perf AT 1 1/2 BPM AT 200 PSI Pump 6 BBLs got circulation behind csg.
10:00	10:30	Plug #2 mix 40SKS cement AT 15.4' got 1/2 BBL returns to surface behind 2" csg. shut in well wash up to muddy to move to any well
2-23-98		
12:00	12:30	Install Dry hole marker

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment _____ Cement Retainers _____

Cementing Plug #1 14SKS Plug #2 40SKSWireline ① 309' - 1 1/16 Biwire