Form.	3160	-5
(Nove:	nber	1983)
Forme	erly	9 - 331)

Form approved.
Budget Bureau No. 1004-0135

	Ехр	ires	Augu	st 31,	1985	
5.	LEASE	DESI	GNATIO	N AND	SERIAL	NO.
	/			26	2	

(November 1983)	SIAIES E THE INTERI	OR verse side)	re Expues	August 31, 1985
	ND MANAGEMENT		Conti	act 362
SUNDRY NOTICES AN	ND REPORTS C	ON WELLS	8. IF INDIAN, Jican	ALLOTTEE OR TRIBE NAME
1.		R 1 7 1985	7. UNIT AGREE	SMAN THEM:
2. NAME OF OPERATOR	BUREAU OF	LAND MANAGED TO	8. FARM OR L	cilla 362 B
Robert L. Bayless 3. ADDRESS OF OPERATOR			9. WELL NO.	1114 302 5
P.O. Box 168, Farmingtor LOCATION OF WELL (Report location clearly and in See also space 17 below.)	n, NM 87499 n accordance with any	State requirements.*	-	POOL, OR WILDCAT
At surface 1550' FSL	& 890' FEL		11. SBC., T., R	ard P.C.
	rions (Show whether DF,	PT CP etc.)	Sec.	7, T23N, R4W
11. 726.012 10.	91' G.L.		!	Arriba NM
18. Check Appropriate	Box To Indicate N	ature of Notice, Report,	or Other Data	
NOTICE OF INTENTION TO:			BERQUENT REPORT OF	/: 
TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  (Other)	OMPLETE	water shut-off  fracture treatment  shooting or acidizing  (Other) Spud &  (Note: Report re Completion or Re	set surface	mpletion on Well ad Log form.)
17. DESCRIBE PROPUSED OR COMPLETED OPERATIONS (CI proposed work. If well is directionally drilled nent to this work.) •				
1-15-85 Spud well at 10:00 a.m. 7" 23#/ft. J-55 used ca surface casing with 47 Circulated cement to th	sing, set at ft³ Class B w	127 ft RKB. Rigge /2% CaCl <sub>a</sub> . Good c	d up Hallibu irculation t	rton. Cemented hroughout job.
-16-85 Drilling @ 595'. W.L.	6.0, Wt 8.6,	Visc. 30. ½° @ 50	0'	
		i	e E : AFRE 4	
			CHL CAT	
			DIST.	3

18. I hereby certify that the foregoing is true and correct SIGNED AM A MON	TITLE Petroleum Engineer	DATE April 16, 1985
(This space for Federal or State office use)	A 1 many and a 1 m	ACCEPTED FOR RECORD
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	ADD 19 1985

APR 10