

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Contract 399

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarrilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Contract 399

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Ballard-P.C.

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

Sec. 24 - T25N - R5W

12. COUNTY OR PARISH 13. STATE

San Juan

N.M.

1. OIL ☐ WELL GAS ☐ WELL OTHER Dry hole

2. NAME OF OPERATOR

B.A. Dodgen

3. ADDRESS OF OPERATOR

Box 215, Rt. #3, Flora Vista, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1850 North of South line

1850 East of West line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6855' - All measurements

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well produced small volume of gas - TSTM - and salty water.

Request permission to plug and abandon.

Will pull approximately 800 feet of 4 1/8-inch casing - Cement top 1205.

Plan to set plug from T.D. 2280 to 2180 ft. - Pictured Cliffs top 2225ft;
set 50-ft. plug in stub of csg and 50-ft. plug above stub;
set surface plug with 5 sacks; and
set 4-ft. conventional dry hole marker.

Clear and level location.

RECEIVED

JUL 12 1968

U. S. GEOLOGICAL SURVEY
SARASOTA, FLA.

18. I hereby certify that the foregoing is true and correct

SIGNED

Lee W. Kilgore

TITLE Agent

DATE July 11, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting or any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-663229

9 67 - 9 5 1

