

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. USA-NM 58871
2. NAME OF OPERATOR PARKO, INC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 903 W. Apache, Farmington, NM 87401	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.) At surface	8. FARM OR LEASE NAME Quinella
RECEIVED MAY 01 1985 BUREAU OF LAND MANAGEMENT FARMINGTON RESOURCE AREA	9. WELL NO. 1
	10. FIELD AND POOL, OR WILDCAT Undes, Gallup
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 31, T23N, R6W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, CR, etc.) GL 7293' KB 7306'
	12. COUNTY OR PARISH Sandoval
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other) Change Production Technique	<input type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Remove and disconnect pump jack and rods. Install and set clock timer with motor valve and use gas plunger lift for production. Rig in for change 4-25-85 and plunger lift started 6:00 AM 4-26-85 with much improved oil and gas production. Producing frac water and oil. Test on this method of production to follow.

Down hole pump was gas locking in bottom and top of hole.

RECEIVED
MAY 03 1985
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Hayd Parker TITLE President DATE 4-29-85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
DATE _____

*See Instructions on Reverse Side