

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Jic. Cont. 440

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla "C"

9. WELL NO.

1 (0-32)

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 32, T.22N., R.5W.

12. COUNTY OR PARISH

Sandoval

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Union Oil Company of California

3. ADDRESS OF OPERATOR

P. O. Box 2620 - Casper, Wyoming 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

660' FSL &amp; 1980' FEL (SW SE)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7271' GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☒CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) Supplementary Well History ☒REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*Drilled to 6330' T.D. Ran Schlumberger Induction-Gamma Ray and Compensated Formation  
Density Logs. J.C. @ 5:30 p.m. 1-13-73.

Propose to plug and abandon subject well as follows:

Plug #1, 35 sacks at 6185-6085'

Plug #2, 35 sacks at 4900-5000'

Plug #3, 35 sacks at 3175-3275'

Plug #4, 35 sacks at 1625-1725'

Plug #5, 35 sacks at 1350-1450'

Displace mud out of hole above top cement plug leaving water in casing.  
Finish POOH w/D.P. Install Dry Hole Marker.Above procedure approved verbally by Jerry Long, U.S.G.S., Durango, Colorado, 1-12-73.  
Top cement plug at surface waived by Emmett Lynch, Bureau of Indian Affairs, Jicarilla  
Apache Indian Agency, Dulce, New Mexico.

18. I hereby certify that the foregoing is true and correct

SIGNED

R. G. Ladd, Jr.

TITLE

District Drilling Supt.

DATE

1-15-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

