SUBMIT IN TRIPLICATE* (Other instructions on re-UNITED STATES

Form approved. Budget Bureau No. #2-R1424.

	DESIGNATION		NO.
NOO-	C = 14 - 2	0 - 3664	

DATE __

DEPARTMENT OF THE INTERIOR verse side)	O. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY	NOO-C-14-20-3664	
	6. IF INDIAN, ALLOYTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)	Navajo Allotted 7. UNIT AGREEMENT NAME	
I. OIL CAS C Dry Hole	7. UNIT AGREEMENT NAME	
WELL WELL OTHER DIY HOLE	8. FARM OR LEASE NAME	
NAME OF OPERATOR	Navajo Allotted 26	
Filon Exploration Corporation 3. ADDRESS OF OPERATOR C/O Minerals Management Inc.	9. WELL NO.	
5. Abbress of Oreston C/O Minerals Management 1110.	1 1	
501 Airport Dr., Suite 105, Farmington, New Mex. 8740 4. LOCATION OF WILL (Report location clearly and in accordance with any State requirements.*	10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface	Wildcat	
	11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA	
ARREST COOL HOL CEC 26 TOIN PAN	Sec. 26, T21N, R7W	
1700' FWL, 600' FSL, SEC. 26, T21N, R7W 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PALISH 13. STATE	
6696 KB	Sandoval N. Mex.	
Check Appropriate Box To Indicate Nature of Notice, Report, or Co.	Other Data	
NOTICE OF INTENTION TO:	QUENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL	
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ABANDONMENT*	
REPAIR WELL CHANGE PLANS (Other) (NOTE: Report result	s of multiple completion on Well	
(Other) Completion or Recom	pletion Report and Log form.)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates proposed work. If well is directionally drilled, give subsurface locations and measured and true vertice nent to this work.) *		
Operator abandoned well as follows:	EOZIVED	
Cement Plugs #1 5925-6075 (150') 75 sx	MAY 4 1976	
#2 4927-5077 (150') 75 sx #3 2645-2795 (150') 75 sx	Company of the second	
#3 2645-2795 (150') 75 sx #4 138- 188 (50') 35 sx #5 0- 30 (30') 15 sx		
Plugs were separated with drilling mud, and an aban was erected 4-29-76.	ndonment marker	
RELIT	•	
WAY 5 1976		
IN COM. COM.		
18. I hereby certify that the foregoing is true and correct Drilling Manager		
18. I hereby certify that the foregoing is true and correct Drilling Manager SIGNED TELLE Minerals Managemen	t Inc _{DATE} 5-3-76	

TITLE .