16.

## UNITED STATES SUBMIT IN TRIPLICATE Budget Bureau No. 42-R142 DEPARTMENT OF THE INTERIOR (Other instructions on respectively) S. LEASE DESIGNATION AND SERIAL NO.

Form approved. Budget Bureau No. 42-R1424.

7 11	 141 -14		O.	•			_
	GEOI	0	GIC	ΔI	SI	IRVE	Y

	ľ	,
Y	Contract No.	413
	& IT INDIAN ALLOWER	OR TRIDE N

	G	EOLOGICAL SURVEY	Contract No.	
	SUNDRY NOTI (Do not use this form for proposi Use "APPLICA"	CES AND REPORTS ON WELLS  alls to drill or to deepen or plug back to a different reservoir.  TION FOR PERMIT—" for such proposals.)	Jicarilla Ar	
ī.	OIL GAS OTHER		7. UNIT AGREEMENT NA	ME
<u>2.</u>	NAME OF OPERATOR		8. FARM OR LEASE NAM	I E
	DAVE M. THOMAS, JR	•	Chacon Jicari	lla Apache "D'
3.	ADDRESS OF OPERATOR		9. WELL NO.	
	P. O. Box 2026	Farmington, N.M. 87401	9	
4. LOCATION OF WELL (Report location cl See also space 17 below.) At surface		early and in accordance with any State requirements.	10. FIELD AND POOL, OF	R WILDCAT
			Chacon Dakota	Associated
	790'FSL, 1850'F	EL	11. SEC., T., E., M., OR E SURVEY OR AREA Sec. 23-T23 N.M.P.M	N-R3W
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	
		7437'GL, 7450'DF, 7151'KB	Sandoval	New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

Check Appropriate Box to material relation of transact, report, or other base						
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS		WATER SHUT-OFF  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  (Other)  (NOTE: Report results of m Completion or Recompletion	REPAIRING WELL  ALTERING CASING  ABANDONMENT®			
(Other)	<u> </u>	Completion or Recompletion	Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1/26/80 Spud Well

1/27/80 T.D. 290'. Ran 6 joints 8-5/8", 24.0 lb. K-55 casing (269.24') set at 283.24' with 250 sacks Class "B" cement with 3% Calcium Chloride and 1/4 lb. Flocele per sack. Cement circulated. Pressure test with 500 psig. Test ok.

T.D. 7705'. Ran 239 joints 4-1/2", 10.50 & 11.60, K-55 2/12/80 casing (7689.28') set at 7703.28' with:

> 440 sacks 50-50 Pozmix with 6-1/4 lbs. First Stage: Gilsonite and 6 lbs. salt per sack.

Second Stage: 125 sacks 65-35 Pozmix (12% Gel) with 6-1/4

lbs. Gilsonite per sack, followed by 50 sacks Class "B" Neat Cement. Stage Collar

at 3380'.

FOR: DAVE M. THOMAS, JR.		COTTON STATE OF THE PARTY OF TH
18. I hereby certify that Gial to real and correct	President, Walsh Eng:	10111111
SIGNED EWELL N. WALSH	TITLE & Prod. Corp.	/ Mulayens
Ewell N. Walsh, P.E.		
(This space for Federal or State office use)		FEB 2 7 1980
APPROVED BY	TITLE	OHLTCON CON
CONDITIONS OF APPROVAL, IF ANY:		DIST
#30 was 1 ***		FF 2.2 1000
FFD 0 ( 100) *C	na Instructions on Reverse Side	1 CD 2001980

FEB 26 '80

Change SISTRICT CAD

state

U. S. GEOLOGICAL SURVEY DURANGO, COLO.