

3100 (016)

Caller Service 4104
Farmington, New Mexico 87499

CERTIFIED

Mr. Robert L. Bayless
P. O. Box 1541
Farmington, New Mexico 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) well No. 2 Jicarilla 393B, SW $\frac{1}{4}$ NW $\frac{1}{4}$ sec. 21, T. 23 N., R. 4 W., Sandoval County, New Mexico, lease Jicarilla Contract 393. No. 2 Jicarilla 392, NE $\frac{1}{4}$ SE $\frac{1}{4}$, sec. 33, T. 23 N., R. 4 W., Sandoval County, New Mexico, Jicarilla Contract 392. As discussed with Kevin McCord of your company on May 21, 1984, the subject APDs are rescinded and returned due to drilling not being commenced within a six month extension period following the original approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,

Lee O. Parson

actg Area Manager

Enclosure

cc: BIA, Dulce
NMOCC
ADO (01537)
Well File (Perm)
DRO 9-1
Suspense (Mason)
Chronological

016:SMason:sd:5/23/84

RECEIVED

MAY 24 1984

OIL CON. DIV.
DIST. 3

ABANDONED LOCATION

Jicarilla 393^B #2

E-21-23N-4W

ROBERT L. BAYLESS

J

30-043-20661

10-29-82

F. Loc. 1820/N; 800/W

Elev. 7020 GL

Spd.

Comp.

TD

PB

Casing S.

@

W

Sx.

Int.

@

W

Sx.

Pr.

@

W

Sx.

I.

@

Csg. Perf.

Prod. Stim.

T
R
A
N
S

I.P. BO/D

MCF/D After

Hrs.

SICP

PSI After

Days GOR

Grav.

1st Del.

s.

TOPS		NITD X	Well Log	TEST DATA						
Kirtland		C-103	Platx	Schd.	PC	Q	PW	PD	D	Ref.No.
Fruitland		C-104	Electric Log							
Pictured Cliffs			C-122							
Cliff House		Ditr	Dfa							
Menefee		Datr	Dac							
Point Lookout										
Mancos										
Gallup										
Sanostee										
Greenhorn										
Dakota										
Morrison										
Entrada										
			160							

P
o
o
i

Ballard PC Co. SA S 21 T 23N R 4W UE Oper. Robert L. Bayless

Loc. Jicarilla 393 B No. 2