Form 3160-5 UNITED S (November 1983) (Formerly 9-331) DEPARTMENT OF	TATES SUBMIT IN TRIPLICA (Other instructions on verse side)	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
BUREAU OF LAND		NM-36929
SUNDRY NOTICES AND (Do not use this form for proposals to drill or t Use "APPLICATION FOR PER	REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL GAS OTHER		- 7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
Diamond Shamrock Exploration c/o Ned Dollar, Agent		Zambarmo Lake Federal
P. O. Box 399 Aztec, NM 87410		9. WELL NO. #41-189
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT
380' FNL & 680' FEL Section 18, T19N., R2W.		Wildcat 11. RBC, T., B., M., OR BLK. AND
RECEIVED		SOC 10 TION DOLL
	S (Show whether DF, RT, GR, etc.)	Sec. 18, T19N-R2W. 12. COUNTY OR PARISH! 18. STATE
NOV 1 8 1985	6949' GR	Sandoval NM
16. Check Appropriate Box	To Indicate Nature of Notice, Report,	or Other Data
BUREAU OF LAND MANAGEMENT INTENTION TO:		REQUENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER O	ASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULTIPLE COMPI	ETE FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANDON® REPAIR WELL CHANGE PLANS	SHOOTING OR ACIDIZING Cement	Program ABANDONMENT*
(Other)		sults of multiple completion on Well ompletion Report and Log form.)
(468 CU ') 50/50 Poz mix	e cmt. to surface. w/Class B. c + 150 sx (177 cu ') Class B.	5½ stage 1; 330 sx Stage 2: 250 sx
(330 Cu) 50/30 POZ III1X	+ 150 sx (177 cu ') Class B.	NOV 2 0 1985 OIL CON. DIV
18. I hereby certify that the foregoing is true and correct SIGNED (This space for Federal or State office use)	TITLE Agent	APPROVED AS 1418 ENDED
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	PATE NUV 1 8 1985
	NMCCD .	MAT MILLENBACH
*	See Instructions on Reverse Side	AREA MANAGER