

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078636 I

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME **Old
Gartner (Harvey Well)**

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

San Luis

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

21 18N 3W

12. COUNTY OR PARISH

Sandoval

13. STATE

New Mexico

1.

OIL WELL ☐ GAS WELL ☐ OTHER

Plugging Well Completed

2. NAME OF OPERATOR

Arwood H. Stowe

3. ADDRESS OF OPERATOR

P O Box 2265, Wichita Falls, Texas 76307

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

2475 s/W 2310 W/E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6785' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

By Letter "Decission - Lease Terminated" the office of Bureau of Land Management Division of Land and Minerals, Program Management and Land Office, Santa Fe, N.M. Terminated the above reference lease. Letter dated July 16, 1968.

Lease was plugged by arrangement with Johnny Myers of Farmington, New Mexico.

Well was plugged September 15, 1968. Location was cleared by Johnny Myers.

Plugging record on attached log.



18. I hereby certify that the foregoing is true and correct

SIGNED

Arwood H. Stowe

TITLE

Operator

DATE

3-22-71

(This space for Federal or State official use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for special instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.
Hard sd rock	0	80	10 ft Surface Cement Plug.
Sh, Cole	80		
& bantonite		480	
sh & sd	480	685	
Sand	685	703	Oil show
Sd, sh	703	795	} Cement plug from 880 to 650
sd	795	810	
sh, sd	810	825	
sd	825	865	Oil show
sd, sh, and			
sd	865	1018	
sd	1018	1032	Oil stain
sd, sh and			
sd	1032	1268	
sd, sh	1268	1379	traces of oil
		1379	TD

→ Plug to 100 ft
1,000 ft
→ To 1250'
129 ft