

9. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p>
<p>1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Disposal Well</u></p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator <u>Dome Petroleum Corporation</u></p>		<p>8. Farm or Lease Name <u>Santa Fe-Barbs</u></p>
<p>3. Address of Operator <u>501 Airport Drive, Suite 107, Farmington, New Mexico 87401</u></p>		<p>9. Well No. <u>1</u></p>
<p>4. Location of Well UNIT LETTER <u>M</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>500</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21N</u> RANGE <u>10W</u> NMPM.</p>		<p>10. Field and Pool, or Wildcat <u>Wildcat-Entrada</u></p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) <u>6404 GR</u></p>		<p>12. County <u>San Juan</u></p>

## Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER Production Casing ☒  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/23/78

Ran 5607", 134 joints, 7", 20# & 23#, K-55, R-3, ST7C casing set at 5607' KB. Cemented first stage w/430 sx 65/35 pozmix w/6% gel, 10# Gilsonite/sk. Followed w/100 sx Class B w/10% salt. Plug down at 10:40 am 10/23/78. Opened DV tool at 3876' and circulated 4 hours. Cemented second stage w/360 sx 65/35 pozmix w/6% gel, 10# gilsonite per sack. followed w/50 sx Class B w/10% salt. Plug down at 3:45 pm 10/23/78. Circulated cement on both stages

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Arnold TITLE Operations Manager DATE 10/31/78

Original Signed by A. R. Smith

APPROVED BY \_\_\_\_\_ TITLE SUPERVISOR DIST. #1 DATE NOV 8 1978

CONDITIONS OF APPROVAL, IF ANY:

