

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	1
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Disposal Well</u>		7. Unit Agreement Name
2. Name of Operator <u>Dome Petroleum Corporation</u>		8. Farm or Lease Name <u>Santa Fe-Barbs</u>
3. Address of Operator <u>501 Airport Drive, Suite 107, Farmington, New Mexico 87401</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>M</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>500</u> FEET FROM THE <u>West</u> LINE, SECTION <u>10</u> TOWNSHIP <u>21N</u> RANGE <u>10W</u> NMPM.		10. Field and Pool, or Wildcat <u>Wildcat-Entrada</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>6404 GR</u>		12. County <u>San Juan</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Production Casing</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/23/78

Ran 5607", 134 joints, 7", 20# & 23#, K-55, R-3, ST7C casing set at 5607' KB. Cemented first stage w/430 sx 65/35 pozmix w/6% gel, 10# Gilsonite/sk. Followed w/100 sx Class B w/10% salt. Plug down at 10:40 am 10/23/78. Opened DV tool at 3876' and circulated 4 hours. Cemented second stage w/360 sx 65/35 pozmix w/6% gel, 10# gilsonite per sack. followed w/50 sx Class B w/10% salt. Plug down at 3:45 pm 10/23/78. Circulated cement on both stages

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Arnold TITLE Operations Manager DATE 10/31/78

Original Signed by A. R. Gonzales TITLE SUPERVISOR DIST. #1 DATE NOV 9 1978

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

