-	n 1 Union Pacifi ^{1 File} UNITED STATE ARTMENT OF THE I JREAU OF LAND MANA	S INTERIOR	BUBMIT IN TRIPLICAT	1 Cramer Oiled Budget Bureau No. 1004-013 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM 36952
(Do not use this form for	NOTICES AND REPO	or plug back to	a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL CAB OTHER WELL OTHER				7. UNIT AGREEMENT NAME
DUGAN PRODUCTION CORP.			Winds - and house	8. FARM OR LEASE NAME FIO-JO
P.O. Box 420, Farm	nington, NM 87499	973 47 A		9. WALL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with an See also space 17 below.) At surface 660 FNL & 1980 FWL			2 S SA	10. FIELD AND POOL, OR WILDCAT South Bisti Gallup Ext. 11. SEC. T. B. M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO. API# 30-045-27441	15. ELEVATIONS (Show v	whether DV, XT, GR.	<u>ana satu</u>	Sec. 1, T23N, R11W, NMPM 12. COUNTY OF PARISH 13. STATE San Juan NM
16. Chec	c Appropriate Box To Inc	dicate Nature	of Notice, Report, or	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17 OLSCRIBE PROPOSED OR COMPLETE proposed work. If well is d nent to this work.)	PCLL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS D OPERATIONS (Clearly state all rectionally drilled, give subsurf	pertinent details	(Note: Report result Completion or Recommendate and give pertinent date	ABANDONMENT* Tace casing & cement X ts of multiple completion on Well pletion Report and Log form.) s, including estimated date of starting any leaf depths for all markers and zones perti-
Spudded a Rigged up a casing (T.E + 2% CaCl ₂ 3-6-90. Ci	.2-1/4" hole at and ran <u>5 jts. 8</u> . 214') <u>set at 2</u> (total cement slu	2:30 P.M. 8-5/8" OD 26' RKB. urry = 17 cement to	on <u>3-6-90.</u> , 24#, 8 Rd, Cemented with Cu.ft.). P. Surface. Pr	Company Rig #14. Drilled to 234'. A53B, smls. ST&C h 150 sx class "B" O.B. at 7:30 P.M. ressure tested 600
			•	ted For Record
			M	AR 3 9 1990

TITLE _

TITLE _

18. I hereby certify that the foregoing is true and correct

Geologist

3-7-90

Mineral Placemes

Fermingias Hésource Area
DATE