

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> DRY HOLE		5. LEASE DESIGNATION AND SERIAL NO. NM 03451	
2. NAME OF OPERATOR DYNA RAY OIL AND GAS CO., INC.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 4101 E. Louisiana Avenue, Denver, Colorado, 80222		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1500' from south line 1020' from west line		8. FARM OR LEASE NAME DUFF	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7301 GR		10. FIELD AND POOL, OR WILDCAT SO BLANCO, PC	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 34-24N-1W	
		12. COUNTY OR PARISH RIO ARRIBA	
		13. STATE NEW MEXICO	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was plugged and abandoned as follows:

1. Ran open end drill pipe in hole to 3040'. Spotted 35 sacks cement through open end drill pipe. Top of cement plug at 2900'.
2. Pulled drill pipe to 2600'. Spotted 30 sacks cement through open end drill pipe. Top of plug at 2500'.
3. Pulled drill pipe to 125'. Pumped 25 sacks out open end drill pipe. Top of cement at 50' inside 8 5/8" surface casing.
4. Erected dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side