

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-03595
2. NAME OF OPERATOR BCO, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 669 Santa Fe, New Mexico 87501		7. UNIT AGREEMENT NAME Escrito
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850 FNL 990 FEL 18-24N-7W NMPM		8. FARM OR LEASE NAME Escrito Unit
14. PERMIT NO.		9. WELL NO. 8
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 7270		10. FIELD AND TOOL, OR WILDCAT Escrito Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 18-24N-7W NMPM
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data (Eliz #1)

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

As reported on subsequent Sundry notice signed 12/14/77, we have a Model A packer with a 30' mud anchor stuck in the hole from 6120 to 6150. The casing from 5880 to 6062 is acid eaten and rotten. We propose to plug w/75 sacks, the Gallup formation from 5920-6138 by setting a packer at 5000' and squeezing said formation with 25 sacks which will leave the top of our cement at about 5700'. Said well will then be permanently plugged from 5700 to T.D. of 7232. Hole condition after plugging will be as follows:
Back-side of 5-1/2 cemented from 7227 to 5700. Cement plug 5700-6138
Drillable plug at 6150. Cement from 7085-7100. Baker cast iron bridge plug at 7100'.

After plugging the Gallup Formation, we intend to temporarily abandon the hole from the surface to 5700'. In 1978 we intend to cement and test selected areas from the Point Lookout up to the Pictured Cliffs. A detailed notice of said testing will be filed prior to commencing same.

18. I hereby certify that the foregoing is true and correct

SIGNED Hurcy R. BighTITLE PresidentDATE 12/15/77

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

