

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator J. Gregory Merrion		8. Farm or Lease Name Edna	
3. Address of Operator P. O. Box 507, Farmington, NM 87401		9. Well No. 2	
4. Location of Well UNIT LETTER O , 990 FEET FROM THE South LINE AND 1650 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 24N RANGE 6W N.M.P.M.		10. Field and Pool, or Wildcat Devils Fork	
15. Elevation (Show whether DF, RT, GR, etc.) 6885 KB		12. County Rio Arriba	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Intend to plug and abandon Gallup Mesaverde side of well as follows:

Pull rods and tubing.
Plug back with sand from 5916 PBD to 5820 above Devils Fork Gallup zone.
Place 30 sacks cement from 5820 - 5426 across Upper Gallup perms 5694 - 5768 and squeeze under packer.
Place 30 sacks cement from 4850 - 4456 across Mesaverde perms 4602 - 4804 and squeeze.
Pull tubing and bull plug top of casing.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Gregory Merrion TITLE Owner/Operator DATE 8-31-79

APPROVED BY AK Henderson TITLE SUPERVISOR DISTRICT #3 DATE SEP 6 1979

CONDITIONS OF APPROVAL, IF ANY: