

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. SF-078959
2. NAME OF OPERATOR BCO, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, New Mexico 87501		7. UNIT AGREEMENT NAME Escrito Gallup
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990 FWL and 790 FSL Sec 7 T24N R7W NMPM		8. FARM OR LEASE NAME Escrito Gallup Unit
14. PERMIT NO.		9. WELL NO. 4 (Formerly Fed 2-7)
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 7163		10. FIELD AND POOL, OR WILDCAT Escrito Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 T24N R7W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Believe well has casing failure. Intend to locate failure and repair. At this time also intend to perforate and pump the cement plugs required for abandonment. Intend to drill out cement and place well back in production. Request that BLM identify plugs required for abandonment and provide to BCO.

Well was drilled in 1961 and 5 1/2" casing was set at 6148' and cemented with 200 sacks of cement. Interval 6006 - 6022 was originally completed. Well was included in water flood project for which Escrito Gallup Unit was formed. Interval between 5806 and 5914 was completed in 1973.

RECEIVED

JUN 19 1991

OIL CON. DIV
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Kashan TITLE President

DATE 5/29/91

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side

NMOCD