

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**
Lease No. **04089**
Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER QUALITY	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO THROAT OR A LIFT	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PUMP UP AFTER CAVING	UPPER CEMENTARY WELL HEAD
NOTICE OF INTENTION TO ABANDON WELL	

X

RECEIVED

DEC 21 1962

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

NOTICE ABOVE REQUIRED FOR ALL WELLS. NOTICE OF OTHER DATA

December 20 1962

Federal
Well No. **19-1-H** is located **990** ft. from **xxx** and **1090** ft. from **xxxxx** line of sec. **19**
SW/4 Sec. 19 **25N** **1W** **N.M.P.M.**
Gavalin P. C. Ext. **Rio Arriba** **New Mexico**

The elevation of the derrick floor above sea level is **7463** ft

DETAILS OF WORK

State number and expected depths to objective sands; show size, weight, and length of proposed tools; indicate mudding jobs, cementing points, and other pertinent work.

It is intended to plug and abandon this well in the following manner:

1. Spot a 15 sk. cement plug across perms (3550'-3604').
2. Find free point and cut 5 1/2" casing.
3. Spot a 15 sk. cement plug across stub and pull casing.
4. Spot a 10 sk. cement plug in top of surface and install a 4' x 4" dry hole marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**

Address **Box 990**

Farmington, New Mexico

By *H. E. McAnally*
Title **Petroleum Engineer**