



CONTINENTAL OIL COMPANY

P. O. Box 3312
Durango, Colorado
June 15, 1962

New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Attn: Mr. E. C. Arnold

Dear Sir:

We are resubmitting the packer leakage test for Jicarilla Apache 22 No. 1.

Erroneous pressures were reported for the two-pen recorder on the previous test submitted for this well. Also, an incorrect pressure was reported for the eight-day shut-in pressure for the Dakota formation. These errors have been corrected on the attached packer leakage test.

We appreciate your bringing this to our attention, and we will attempt to prevent errors of this nature in the future.

Yours very truly,

A handwritten signature in cursive script, appearing to read "H. D. Haley".

H. D. Haley
District Superintendent
Durango District
Production Department

MAM/cb

