

Mountain States Petroleum Corp.

P. O. Box 1362

TULSA, OKLAHOMA

ALBERT J. BLAIR, JR.
President

Telephone: Diamond 3-9574

December 22, 1959

New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Re: Well Record Form C-105
Our Walter Howard #2 Well
NE/4 NE/4 Sec. 22 T25N R2W, NMPM
Rio Arriba County, New Mexico

Gentlemen:

We are enclosing an original and four copies of the subject report on the Howard #2 Well in Rio Arriba County, New Mexico.


Respectfully yours,

MOUNTAIN STATES PETROLEUM CORP.

By:

Albert J. Blair, Jr.
Albert J. Blair, Jr.

AJB Jr/lp
enc.



New Mexico Oil Conservation Commission

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

December 29, 1959

Mountain States Petroleum Corporation
P.O. Box 1362
Tulsa, Oklahoma

Attn: Mr. Albert J. Blair, Jr.

Dear Mr. Blair:

We have just received Form C-104, Well Record Form, for your #2 Walter Howard well in the NE¹/₄ Section 22-25N-2W. In checking our file we find that you have not complied with the New Mexico Oil Commission Rules and Regulations in the following instances:

First, Form C-103 has not been filed showing that casing tests were run on either surface or production casing strings, as required by Commission Rule 107. This rule states "On all wells drilled with rotary tools the casing shall be tested with pressure of not less than 600 pounds per square inch for a period of not less than 30 minutes." The rule further states that if a drop of more than 10% of the test pressure should occur the casing shall be considered defective and corrective measures shall be applied.

You have also stated on the Well Record Form that an attempt to fracture was made through perforations 3372-80' and that it was found that communication existed with the open hole. If communication exists between the pay zone and the annulus behind the casing immediate steps should be taken to squeeze the perforations so that the pay zone is permanently separated. We are, therefore, directing that this be done immediately. If you have any questions regarding the above matter, please contact this office.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

cc: Mr. A. L. Porter
OCC, Santa Fe, N.M.

ASTED, NEW MEXICO

Journal of Management Inquiry 18(6)

RECEIVED
JAN 10 1964
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION

[illegible]

44:55 - 11:12

1. The first step is to identify the problem. This involves understanding the current situation and the goals that need to be achieved.

...the ...
...the ...
...the ...
...the ...
...the ...
...the ...
...the ...

...of the
... ..
... ..
... ..
... ..
... ..
... ..

Wirtz, 1994, p. 101

10-10-1964

100

1970-1971