

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 079600

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

J. J. Roberts

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Point Lookout, Mesa Verde
11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 13-25N-3W

12. COUNTY OR PARISH 13. STATE

Mo Arriba

N. M.

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Skelly Oil Company

3. ADDRESS OF OPERATOR

Rm. 208 Goodstein Bldg. 330 So. Center, Casper, Wyo. 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 1190' PSL and 1450' PSL, Sec. 13-25N-3W

14. PERMIT NO.

NA

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7142' SL, 7152' AS

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

☐
☐
☐
☐
☐

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐
☐

Test Point Lookout
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Nov. 5, 1973; Spotted 25 sks. cement over Dakota Perfs. from 8144'-7925'. Squeeze Job. No. 1, perforated 5 1/2" csg. w/2 shots at 5900', squeezed perfs. w/150 sks cement. Ran Bond log found cement at 5850'. Squeeze Job. No. 2; Perforated 5 1/2" csg. w/2 shots at 5850'. Squeeze w/150 sks. cement. Ran Bond log found cement at 5830'. Squeeze Job No. 3; Perforated 5 1/2" csg. at 5828', Squeezed w/150 sks. cement. Ran Temp. Survey, found top of cement behind csg. at 5650'. Top of cement inside csg. at 5689'. Ran tbg. w/bit drilled cement to 5841' PBTD. Perforated 5 1/2" csg. 2 shots per ft. from 5808-5828' (Point Lookout). Treated perfs. 5808-29' w/17336 gals. water and 17336# sand. Job complete 12-13-73.



18. I hereby certify that the foregoing is true and correct

SIGNED

Ray H. Haskins

TITLE

Area Supt.

DATE

Apr. 10, 1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 17 1974

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below, or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal Requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of packing of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1941-O-685229

947-485

