
Form 9-331 a (Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No.	NM 05942-1

Unit Bolack

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF. SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OF REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHEC	CK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
	August 19 , 19 63
	t. from $\begin{Bmatrix} \mathbf{N} \\ \mathbf{S} \end{Bmatrix}$ line and 2120 ft. from $\begin{Bmatrix} \mathbf{K} \\ \mathbf{W} \end{Bmatrix}$ line of sec. 13
NE/4 SW/4 Sec. 13 25N	lw N.M.P.M.
(% sec. and sec. No.) (Twp.)	(Range) (Meridian)
Undesignated (Field)	Rio Arriba New Mexico (County or Subdivision) (State or Territory)
ing points, a	show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement- and all other important proposed work)
6-12-63 TD 6022' RKB. 8 J-55 casing at 5	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks coment.
6-12-63 TD 6022' RKB. 5 J-55 casing at 5 6-13-63 Temperature surv	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks coment. vey showed top of cement at 4500'.
6-12-63 TD 6022' RKB. 5 J-55 casing at 5 6-13-63 Temperature surv	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks coment.
6-12-63 TD 6022' RKB. S J-55 casing at 5 6-13-63 Temperature surv 6-17-63 Pressured up on	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks cement. vey showed top of cement at 4500'. casing to 1000#. No pressure decrease
6-12-63 TD 6022' RKB. S J-55 casing at 5 6-13-63 Temperature surv 6-17-63 Pressured up on in one hour.	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks cement. vey showed top of cement at 4500'. casing to 1000#. No pressure decrease AUG 21 1963
6-12-63 TD 6022' RKB. S J-55 casing at 5 6-13-63 Temperature surv 6-17-63 Pressured up on in one hour.	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks cement. vey showed top of cement at 4500'. casing to 1000#. No pressure decrease
6-12-63 TD 6022' RKB. S J-55 casing at 5 6-13-63 Temperature surv 6-17-63 Pressured up on in one hour.	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks coment. vey showed top of cement at 4500'. casing to 1000#. No pressure decrease RICEVED AUG 21 1963 roval in writing by the Geological Surveyletge Mail Gold to commenced. DIST. 3
6-12-63 TD 6022' RKB. S J-55 Casing at 5 6-13-63 Temperature surv 6-17-63 Pressured up on in one hour. I understand that this plan of work must receive appropriately be a second of the second of th	Set 186 joints 5967' of 5-1/2" OD 15.5# 5976' RKB with 150 sacks cement. vey showed top of cement at 4500'. casing to 1000#. No pressure decrease AUG 21 1963 royal in writing by the Geological survey before Maria Commenced. DIST. 3