


Form 9-331a
(Feb. 1951)



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 080565
Unit NE 1/4 Section 5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	<input type="checkbox"/>
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL.....		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 15, 1956

Florasce

Well No. 2 is located 990 ft. from N line and 900 ft. from E line of sec. 5

NE 1/4 5 25N 3W N.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

W.C. Rio Arriba N.M.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7289 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

October 2, 1955

Run 3830' 5 1/2" New 15.5# 8rd Casing

Cemented 100 Sax Rag, Pressured 800# 15" no Loss



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Counsight Butte Uranium Corp.

Address Box 1208

Farmington, New Mexico

By John A. Egan

Title Agent