## STATE OF NEW MEXICO ENERGY and MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION

Page 1 Revised 10/01/78

This form is not to be used for reporting packer leskage tests in Southeast New Mexico

## NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

perator <u>S</u>	OUTHERN UNI	ON EXP. CO	Lease _	JICARILLA	К	We No.	16
cation Well: Unit_	D Sec. 12	Twp. 25N	Rge	5W	Co	unty R	O ARRIBA
	NAME OF RESERVOIR OR POOL			TYPE OF PROD. (Oil or Gas)		DD.	PROD, MEDIUM (Tbg. or Cag.)
Upper mplation O				GAS			csg.
ower optetion B	MAGES   GAUGEA			GAS			TBG
<del> </del>	***************************************	PRE-FL	OW SHUT-IN P	RESSURE DATA		4	
PPET Plation 08/02/91 Length of time shut 5 DAY				81 press, paig		Stabilized? (Yes or No) VES	
Hour, date shul-in Lipitelon 08/02/91.		Length of time shi		Si press, psig	770 Stabilized		(Yes or No)
			FLOW TEST	<u>N</u> O. 1			
imenced at (hour, date) *  TIME LAPSED TIME			PRESSURE		Zone producing (U r .w Lower): PROD. ZONE		ARKS
(hour, date)	SINCE*	Upper Completion	Lower Completion	TEMP.			
/03/91	24	165	735	0	<u> </u>		***************************************
/04/91	24	165	750	0	-		
3/05/91	24	165	770 .	0	DAK. ON		
7/06/91	24	165	325	0			
/07/91	24	165	300	0			
//	0	0	¹ O	. 0			
uction fate 0 85	during testBOPI	O D baseda MCFF	Bbls. in	0	ME	O.C Grav ETER	00 0 GOR
		•		ESSURE DATA	/·		
Hour, date shut-in		Length of time shut		Stabilized? (Yes or No		(es or No)	
Hour, date shut-in		Length of time shul	Length of time shut-in			Stabilized? (	(es or No)

JIL CON. L

		NO. 2  Zone producing (Upper or Lower):			
TIME LAPSED TIME	PHESBURE		PROD. ZONE		
fhour, date) BINCE 本本 Upper	Completion	Lower Completion	TEMP.	REMARKS	
			1		
	<u> </u>				
	<del></del>				
			İ		
		Marka + 4 A A A A A A A A A A A A A A A A A A			
	-				
				The state of the s	
uction rate during test		1			
rks:			Orifice or Meter):		
by corrife that the information I	·				
by certify that the information herein	) containe	d is true and com	plete to the best of m	y knowledge.	
oved AA 6 333	<del></del>	•	erator Doct Ch	En Union Exp	
		Ву	2 Vatter	Cull	
Walter San of her DEAMES CHO		Tid	· Pumper		
PERUTY ON & GAS INSPECTOR.			i		

## NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been distrubbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal tate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 3. Following completion of Flow Test No. 1, the well shall-again be shut-in, in accordance with Paragraph 3 above.
- 6 Flow Test'No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except

- that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately priot to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hously intervals thereafter, including one pressure measurement immediately priot to the conclusion of each flow period, 7-day tests: immediately priot to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately priot to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 13 days after completion of the test. Tests shall be filed with the Astec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).

and the first