Form 3160-5 (November 1983)	UNITED	STATES	SUBMIT IN TRIPL	CATE.	Budget Bureau No. 1004-0135 Expires August 31, 1985
Formerly 9-331)	DEPARTMENT O		(Other instructions verse side)	OB 12-	LEASE DESIGNATION AND SERIAL NO.
		ND MANAGEMENT		-,	CONTRACT 11
SUND (Do not use this fo	ORY NOTICES AP	ND REPORTS OF	N WELLS It to a different recervoir	1	
F	orm for proposals to drill Use "APPLICATION FOR	PERMIT—" for such prop	oenis.)		JICARILLA APACHE
OIL GAS WELL X	OTHER			ĺ	. Out soldings high
2. HAMB OF OPERATOR					. FARM OR LEASE HAMB
AMERADA HESS CO	RPORATION				J. APACHE "B"
DRAWER D, MON	UMENT, NEW MEXIC	0 88265			16
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At auriace					O. FIELD AND POOL, OR WILDCAT
K				\ _ 1	BALLARD PICTURED CLIFF 11. SEC., T., R., M., OB BLE. AND SURVEY OR ARRA
1850' FSL & 150	O' FWL				
14. PERNIT NO.	15. BLEVA	nons (Show whether DP, R	T, GR, etc.)		SEC. 29, T-24N, R-5W 2. COUNTY OR PARISE 13. STATE
	65	95' GR		F	RIO ARRIBA NM
16.	Check Appropriate	Box To Indicate Na	ture of Notice, Repoi	t, or Oth	er Data
но	TICE OF INTENTION TO:	1		eu bebque n	T REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALT	ER CASING	WATER SHUT-OFF		ESPAIRING WELL
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE CO	MPLETE	FRACTURE TREATMEN SEGOTING OR ACIDIZ	 	ALTERING CASING
REPAIR WELL	CHANGE PLAN	ıs —	(Other)		
	PLANS		Completion or	Kecomplett:	multiple completion on Well on Report and Log form.)
proposed work. If the nest to this work.)	well is directionally drilled,	early state all pertinent (give subsurface location	details, and give pertinen ns and measured and tru	t dates, in e vertical o	cluding estimated date of starting any lepths for all markers and sones perti-
SIGNED (This space for Federal APPROVED BY CONDITIONS OF APP	or State office use)		PETROLEUM ENGII		10/23/90 A PAR O V E D
			i		NOV 0 5 1990
		*See Instructions o	n Reverse Side		AREA MANAGER