

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

3 NMOCD 1 File 1 McHugh, Fmn
OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

McHugh, Denver

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name	
2. Name of Operator DUGAN PRODUCTION CORP.		8. Farm or Lease Name McDug	
3. Address of Operator P O Box 208, Farmington, NM 87499		9. Well No. 1	
4. Location of Well UNIT LETTER C, 790 FEET FROM THE North LINE AND 1850 FEET FROM THE West LINE, SECTION 9, TOWNSHIP 25N, RANGE 2W, NMPM.		10. Field and Pool, or Wildcat Gavilan P.C.	
15. Elevation (Show whether DF, RT, GR, etc.) 7336' GR		12. County Rio Arriba	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well was plugged in the following manner:

1. Spotted 12 sx (14 cf) cement plug from 3706-3548'.
2. Rigged up casing jacks and found free point.
3. Shot 4½" casing off @ 759'.
4. Spotted 13 sx (15 cf) cement plug 809 - 709' - 50' inside 4½" casing stub and 50' above 4½" casing stub.
5. Spotted 19 sx (22.42 cf) cement plug 195' to 93' - from 50' below surface casing to 50' inside surface casing.
6. Installed dry hole marker with 5 sx cement.

Job complete 10-5-85.

NOV 27 1985

OIL CON. DIV.
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jim L. Jacobs TITLE Geologist DATE 11-26-85

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUL 18 1986

CONDITIONS OF APPROVAL, IF ANY: