

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR  
Getty Oil Company
3. ADDRESS OF OPERATOR  
P.O. Box 3360, Casper, Wyoming 82602
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1600' FSL & 1850' FEL of Sec 31  
AT TOP PROD. INTERVAL: SAME  
AT TOTAL DEPTH: SAME
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO:                      | SUBSEQUENT REPORT OF:    |
|---|--------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/>  | <input type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/>       | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/>     | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/>          | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/>    | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/>         | <input type="checkbox"/> |
| ABANDON* <input type="checkbox"/>             | <input type="checkbox"/> |
- (other) Temporary shut-in of Gallup Zone

5. LEASE  
Contract #68
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
Jicarilla Apache
7. UNIT AGREEMENT NAME  
-----
8. FARM OR LEASE NAME  
Jicarilla "B"
9. WELL NO.  
#26E
10. FIELD OR WILDCAT NAME  
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
J, Sec. 31-T25N-R5W
12. COUNTY OR PARISH  
Rio Arriba
13. STATE  
New Mexico
14. API NO.  
-----
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6757' Graded GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The Gallup Zone was temporarily abandoned on 11-29-83 because the bottomhole pressure was insufficient to commingle both the Dakota and Gallup Zone. The production string was run in the hole with a sliding sleeve above a permanent packer. We are currently testing the Dakota to determine the possibility of commingling both zones. Prior to this temporary shut in, flow testing of the Gallup was being conducted. Proper filings will be made upon completion of testing of the Dakota.

RECEIVED

JAN 06 1984

OIL CON. DIV.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ DIST. 3 Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Superintendent DATE 12-6-83

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JAN 06 1984