Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

/	FORM APPROVED
	OMB NO. 1004-0135
Ex	pires: November 30, 2000

5. Lease Serial No.

8914

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE -	7. If Unit or CA/Agreement, Name and/or I Lindrith Unit	
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator		8. Well Name and No. Lindrith Unit 112
ENERGEN RESOURCES CORPORATION Ba. Address	3b. Phone No. (include area code	30-039-23021
2198 Bloomfield Highway, Farmington 4. Location of Well (Footage, Sec., T., R., M., or Survey I 1180' FSL, 880' FEL, Sec. 26, T24N,	Description)	10. Field and Pool, or Exploratory Area South Blanco Pictured Cliffs
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF NOTICE	Rio Arriba NM CE REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	
X Notice of Intent	Acidize Deepen	Production (Start/Resume) Water Shut-Off
Subsequent Report	Alter Casing Fracture Treat X Casing Repair New Construction Change Plans Plug and Abandon	Reclamation Well Integrity Recomplete Other Temporarily Abandon
Final Abandonment Notice	Convert to Injection Plug Back	Water Disposal

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

It is intended to test for a casing leak as follows:

- 1. MIRU. TOH with tubing.
- 2. Pick up 2 3/8" workstring and packer. TIH to top of perfs and test casing to 500 psi.
- 3. If test fails, isolate leak and squeeze cement with sufficient amount of cement to isolate leak.
- 4. Drill out squeeze, Test casing to 500 psi.
- 5. TIH and clean out to PBTD. TOH and lay down workstring.
- 6. Rerun tubing and return to production.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Vicki Donaghey	itle Production Assistant	
Vicki Monaghau	Date 2/25/02	
THIS SPACE FOR FEDERAL	OR STATE OFFICE USE	
Approved by /s/ Patricia M. Hester	Title Lands and Mineral Resources	Date MAR 2 2002
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject least which would entitle the applicant to conduct operations thereon.	r Office	