

Additional data for EC transaction #11800 that would not fit on the form

32. Additional remarks, continued

5/7/02 CSG 0#; TBG 0#. RU & swab 310'. Pull 5 stds tbg. Tried to swab but could not get swab in the tbg tried to pmp DN tbg could not pmp through tbg. RU mud bucket. SI SD FN.

5/13/02 Tbg 0, CSG 0. Pulled 7 stds tbg came wet w/oil & water. Tried to swab could not get swab cups in tbg. RD swab. Build an 18" dike around well head. TOH w/CIBP. PU & TIH w/new CIBP & set @ 7265'. Press tst csg w/rig pmp to 550# held good. Bled off press SI SD FN.

5/14/02 Tbg 0# Csg 0#. Circ hole. RU FMC recorder press tst to 550# held press for 30 min. Test good. TOH w/setting tool. TIH w/2 3/8" tbg open ended landed 1 jt above CIBP 232 jts. RD floor. ND BOP NU Well Head. RD Equip. SISDFN

5/15/02 Service unit. wash rig. RD Rig equipment. Well T&A'd

Revisions to Operator-Submitted EC Data for Sundry Notice #11800

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	TA SR	TA SR
Lease:	JIC CONT 148 17Y	JIC148
Agreement:		
Operator:	BP AMERICA PRODUCTION COMPANY P.O. BOX 3092 ROOM 19.178 HOUSTON, TX 77253 Ph: 281.366.4081 Fx: 281.366.0700	BP AMERICA PRODUCTION COMPANY PO BOX 3092 HOUSTON, TX 77253 Ph: 281.366.4081
Admin Contact:	CHERRY HLAVA AUTHORIZED REPRESENTATIVE E-Mail: hlavacl@bp.com Ph: 281.366.4081 Fx: 281.366.0700	CHERRY HLAVA AUTHORIZED REPRESENTATIVE E-Mail: hlavacl@bp.com Ph: 281.366.4081 Fx: 281.366.0700
Tech Contact:		
Location:		
State:	NM	NM
County:	RIO ARRIBA	RIO ARRIBA
Field/Pool:	LINDRITH GALLUP DAKOTA, WEST	W LINDRITH
Well/Facility:	JICARILLA CONTRACT 148 17Y Sec 15 T25N R5W NWSE 990FSL 790FEL	JIC APACHE 43(17Y) Sec 15 T25N R5W SESE