

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Taurus Exploration, U.S.A., Inc.

3. Address and Telephone No.
2198 Bloomfield Highway; Farmington, NM 87401

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1650' FNL, 1780' FEL, Sec. 22, T25N, R3W, NMPM

AFMSS

Adj	(initials)
Engr	(initials)
Geol	(initials)
Surf	(initials)
Appvl	(initials)

5. Lease Designation and Serial No.
NM-04075

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Arco Hill #1

9. API Well No.
30-039-23838

10. Field and Pool, or exploratory Area
Blanco Mesa Verde

11. County or Parish, State
Rio Arriba NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

RECEIVED
MAY 23 1998

OIL CON. DIV.
DIST. 3

Notified Cuba BLM on 3/12/98.

3/13/98 Lower tbg. and tag tbg stub at 5060': Load csg with 30 bbls water and pressure test csg. 500# for 5 min, held ok. Plug #1: 17sxs Class B cement from 5120' to 4970' to cover 2 7/8" tbg. stub.

3/17/98 RIH with 5 1/2" gauge ring and tag cement at 4894'. Perforate 3 squeeze holes at 3827'. Set retainer at 3764'. Attempt to establish rate into squeeze holes, pressured at 6 bbls. to 1500#. Unable to pump into. Al Yepa with Cuba BLM approved procedure change. Plug #2 with retainer at 3764', spot 54 sxs Class B cement inside csg above retainer to 3340' to isolate Pictured Cliffs top and cover Fruitland, Kirtland and Ojo Alamo tops. Perforate 3 squeeze holes at 1780'. Set 5 1/2" retainer at 1720'.

Establish rate into squeeze holes 1 BPM at 1000#. Plug #3 with retainer at 1720; mix 46 sxs Class B cement, squeeze 29 sxs outside 5 1/2" csg. from 1780' to 1680' and leave 17 sxs inside csg. to 1620' to cover Nacimiento top. Perforate 3 squeeze holes at 554'. Establish rate out bradenhead 2 BPM at 0#.

Plug #4 with 175 sxs Class B cement pumped down 5 1/2" csg from 554' to surface, pressured up when pumping down csg, shut in csg with 800# and pump 2 bbls cement into bradenhead; pressured up, shut in with 800# and WOC overnight.

3/18/98 Cut off wellhead, cement down 10' in 5 1/2" csg and 8 5/8" annulus. Mix 28 sxs Class B cement to fill casings and install P & A marker. Note: Al Yepa, Cuba BLM was on location.

14. I hereby certify that the foregoing is true and correct
Signed Don Graham Title Production Foreman
Approved by Patricia M. Kester Title Lands and Mineral Resources
Conditions of approval, if any: COA's for Surface restoration in attached letter original sent to Meridian Date 4/7/98

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.
Date 5/17/98
Date NOT 6/11/96
* See Instruction on Reverse Side

