

## STATE OF NEW MEXICO

## ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

GARREY CARRUTHERS
GOVERNOR

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

Date: 9-26-87
Oil Conservation Division P.O. Box 2088 Santa Fe, NM 87504-2088
Re: Proposed MC Proposed DHC Proposed NSL_X Proposed SWD Proposed WFX Proposed PMX
Gentlemen:
I have examined the application dated 9-18-87
for the BANNEN ENERGY INC. LYBROOK 19-219 Operator Lease & Well No.
Operator Lease & Well No.
1-19-27W-612 and my recommendations are as follows:
Hpprove
N56-276/
Yours truly,
Soll and the second

BANNON ENERGY INCORPORATED

SEP1 8 1989

OIL CON

3934 F.M. 1960 West, Suite 240 Houston, Texas 77068 (713) 537-9000 FAX (713) 537-8624

August 16 1989

Mr. Mine Stodner Energy and Minerals Dent. Dil Conservation Division 310 Old Santa Fe Trais. Root 166 Santa Fe New Mexico 37503

Approval of Non-Standard Constion - Appropriate 2157' PS :: 2004' WW.

Ser. 19, TRAM, R6W. Devils Fort Galling F. Col

Rio Arriba County, New Mexico

Den My Singner

RE:

Please accept this letter as request for approved of one organized location for the above references well. This well is being differed as a replacement well for the Tubrook (4-2 which would receive problems of the teferences of

The arcticeological correspond conducted on value  $S_{\rm c}$  is  $C_{\rm c} = 0.00$  as on  $C_{\rm c}$  was staired at the above referenced location. We removed their arcticus expension based as the following:

The Division of Conservation Archeology of the San Coan County Museum Association conducted in archeological survey of the obtained area. One site was located during the survey plong the eastern leade of the cultural buffer none on the southeast side of the proposed Lybroak FD Th well bad. The lepoit no. 1678 ATTACHMENT NO. I resommended clearance for the proposed well bad and access coad/pipeling

Bannon operates the west stimet well. (Lyonook of the ne plugged which is located to the southwest surproximately 20% feet of the suspessor well. Since the Devils Fork Gallur pook is spaced on the new monofinet drainage problems will exist

Mr. Mike Stogner

RE: Lybrook 19-2R Non Standard Location

August 16. 1989

Page 1

ATTACHMENT NO. 2 is a map of offset leases within a one mile radius of the proposed location. The offset operators have been sometimed to did not standard location request, and copies of the registered receiving are shown as ATTACHMENT NO. 3

Should you have any questions regarding this mait in the Teace call. Brad Salzman at (505) 326-0550. Thank you for your consideration in this matter.

Sincerely

W. J. Holcomb Operating Agent.

Bannon Energy, Iro.

WJH: ck

Attachments

co: Eroie Busco

NMOCD - Aztec, New Ment of


## ABSTRACT

On June 28, 1989, the Division of Conservation Archaeology of the San Juan County Museum Association completed an archaeological survey of proposed well pad Lybrook 19-2R and access road/pipeline for Bannon Energy, Inc. The survey area is located northeast of Lybrook, Rio Arriba County, New Mexico and is under the jurisdiction of the Navajo Nation with a fee surface and with minerals under the jurisdiction of the Bureau of Land Management. Approximately 5.74 acres were intensively inventoried.

One site, DCA-89-365, was located during survey of the project area. The site is a Navajo Dinetah lithic and ceramic scatter located along the eastern edge of the cultural buffer zone on the southeast side of the proposed Lybrook 19-2R well pad.

Archaeological clearance is recommended for the proposed Lybrook 19-2R well pad and access road/pipeline.

ATTACHMENT TO EXHIBIT "E"



3. Cement circula	the foregoing is true and correct	رار ۱۱ر	CON. 5 DIST. 3  Holcomb for Bannon En		FOR RECU	
3. Cement circula		رار ۱۱ر	DIST. 3	ergy n	e co	1
3. Cement circula		ر کرد ۱۱۰	DIST. 3		90 H King C 20 C 2	
3. Cement	:	gris. La				
3. Cement	:	32 <b>3 2</b>			2	
3. Cement	ace /o Br., ceme					
	2 1/4" surface h joints 8 5/8" 24 with 190 sx. Cl	4# at 301'.	ent and 1/4# o	cello se	eal,	
7. DESCRIBE PROPUSED OR	COMPLETED OPERATIONS (Clearly well is directionally drilled, gi	ly state all pertinent de ive subsurface locations	completion of Reco	hapletion Repo	ort and Log form.)	·
REPAIR WELL (Other)	CHANGE PLANS		(Other) Set Sur	ults of multin	le completter es	
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMP		WATER SHUT-OFF FRACTURE TREATMENT		BEPAIRING WEL	
	NOTICE OF INTENTION TO:			SEQUENT REPORT	RT OF:	
6.	697	'q' GR		Rio A	Arriba	NM
Unit K;	2122' FSL and	1707 FWL	(III etc.)	Sec.	19 T24N R6	W
At surface	·		te requirements.*	Devi	LD AND POOL, OR W LS Fork-Gal	.lup
c/o Holcom	b Oil & Gas, In	c PO Box 20	58 Farmington	NM 9. WELL	ло. 2R	
Bannon Ene	rgy, Incorporat	ed		Lybro	ook 19	
OIL GAS WELL OTHEE  2. NAME OF OPERATOR					7. UNIT AGESEMBNT NAME	
	form for proposals to drill or Use "APPLICATION FOR PE	to deepen or plug back	WELLS to a different reservoir.	6. IF 18	DIAN, ALLOTTEE Q	R TRIBE N
(Do not use this	IDRY NOTICES AND	) REPORTS ON				
(Do not use this	BUREAU OF CAND	D REPORTS ON		SF-0	E DESIGNATION AND 78562	D SPEIRL

\*See Instructions on Reverse Side

FARMHATON RESOURCE AREA