

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
 (Other instructions on reverse side)

Bureau Form No. 1004-0135
 Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
 Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-078534																				
2. NAME OF OPERATOR BCO, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME																				
3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, NM 87501		7. UNIT AGREEMENT NAME																				
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1850' FNL and 930' FWL SEC 31, T24N, R6W, NMPM		8. FARM OR LEASE NAME Bobby B																				
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6718' GL	9. WELL NO. 3																				
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		10. FIELD AND POOL, OR WILDCAT Escrito Gallup Associat.																				
<table border="0"> <tr> <td>TEST WATER SHUT-OFF</td> <td>☐</td> <td>WATER SHUT-OFF</td> <td>☐</td> </tr> <tr> <td>FRACURE TREAT</td> <td>☐</td> <td>FRACURE TREATMENT</td> <td>☐</td> </tr> <tr> <td>SHOOT OR ACIDIZE</td> <td>☐</td> <td>SHOOTING OR ACIDIZING</td> <td>☐</td> </tr> <tr> <td>REPAIR WELL</td> <td>☐</td> <td>REPAIRING WELL</td> <td>☐</td> </tr> <tr> <td>(Other)</td> <td>☐</td> <td>(Other)</td> <td>☐</td> </tr> </table>		TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐	FRACURE TREAT	☐	FRACURE TREATMENT	☐	SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐	REPAIR WELL	☐	REPAIRING WELL	☐	(Other)	☐	(Other)	☐	11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA SEC 31, T24N, R6W, NMPM
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐																			
FRACURE TREAT	☐	FRACURE TREATMENT	☐																			
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐																			
REPAIR WELL	☐	REPAIRING WELL	☐																			
(Other)	☐	(Other)	☐																			
		12. COUNTY OR PARISH Rio Arriba																				
		13. STATE NM																				

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

DEFECTIVE ID

MAY 29 1990

OIL CON. DIV.

Complete & Place in Production

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

5/4/90 . Moved rig to location. Picked up tubing to drill out cement. Tagged cement at 4534'. Tagged DV tool at 4633'. Drilled DV tool. Tagged float at 5593' which is PBTD. Rolled hole with KCL. Came out of hole with tubing.

5/7/90 . Halliburton Logging Services logged cement from 5050' to 5556' and 4500' to 4750'. Halliburton Logging Services will mail two copies of the Cement Bond Log to the BLM and one copy to the OCD. Pressure tested at 2500 lbs for 30 minutes. Pressure held. Perforated with one 3-1/8" 0.39" select fire shot at 5264', 5267', 5391', 5394', 5397', 5403', 5406', and one 3 1/8"; 0.32" select fire shot at 5433', 5442' and 5462'.

5/7/90 & 5/8/90 . Went in with straddle packers. Spotted 1000 gallons 7 1/2% HCL double inhibited acid. Broke down each perforation.

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth B. Keeshan

TITLE Vice President

DATE 5/16/90

(This space for Federal or State office use)

APPROVED BY
 CONDITIONS OF APPROVAL, IF ANY:

TITLE

NMOCD

ACCEPTED FOR RECORD

DATE
MAY 17 1990

FARMINGTON RESOURCE AREA

BY

*See Instructions on Reverse Side